RTR Services Inc. BOX TRUCK CONDITION REPORT											RTR #: 3023401-01 ACCOUNT NUMBER: ACCOUNT NAME:										
<b>YEAR:</b> 2018			MILES 311,543						VIN#: 3HAMMMLXJL569505												
MAKE:		International		GV	<b>GVW:</b> 25,999			X HEIGH	т	13'6"	6" BOX LENGTH 26'			BOX WIDTH 102"							
MODEL:		4300		WH	IEELB.	ASE:			C	COLOR: EXTERIOR: White				INTERIOR: Gray							
EI	NGINE:	Cummins ISB 6.7I					KI			EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR:					<b>:</b> 🖂						
т	RANS:	Automatic	FU		GAS 🖂	DIESE															
		OTOR RUN?	🛛 YE			-			-						AGE? 🛛 YES						
				-		-				L APPEARANCE								_			
		GD	FR	PR	N/A	COM	IENTS										(	DPT	ONS		
ВОДУ	-	BUMPER														_	PWR STEERING				
	HEAD LIGHTS HOOD TURN SIGNALS			$\boxtimes$											BRAKES						
				$\boxtimes$																	
	GRILL																=	PWR L			
	D FRONT FENDER D DOOR			$\boxtimes$														PWR W PWR S			
	D BOX	ix iii			$\square$													PWR M		-	
	REAR		$\boxtimes$																TIONER		
	TAIL LIGHTS			$\square$		$\square$											$\square$			EAT D/P <u>d</u> USPENSION	J
	P FRONT FENDER																	AM FM	-		
	P FRONT DOOR			$\boxtimes$				-									_			/ CB?	-
	P BOX TOP			$\boxtimes$			Dama Box d		Dor	Donted and holes						SLEEPER SIZE?				-	
TIRES	D FRONT							Box damaged. Dented and holes % 40 SIZE: 11R22.5							E-TRACK LINING						
	D REAR A1 (S/D?)			$\boxtimes$				40 SIZE:	11R	22.5								BOX D		-	
	D REAR A2 (S/D?) P FRONT			$\square$		$\square$		SIZE: SIZE: 11	R22	5								SIDE D		ł	
	P REAR A1 (S/D?)			$\boxtimes$				40 SIZE:												GAL <u>70</u> _	
		P REAR A2 (S/D?)				$\boxtimes$		SIZE:													
	SPARE WINDSHIELD						% Crack	SIZE:										MUD FI		5	
SS	D FRONT DOOR			$\boxtimes$			oraon												MIN	UM	
ຊິ REAR ໆ P FRO MIRRO		WINDOW		$\boxtimes$																	
				$\boxtimes$																	
	DASH			$\boxtimes$														EXHAU	ST S	S/D? <u>S_</u>	
R		DOOR PANELS SEAT(S)		$\boxtimes$													SUS		N		
RIOR	FLOOR			$\boxtimes$															ING		
INTE	HEADL	HEADLINER		$\boxtimes$															)		
=	SLEEPER BOX						Damaged										□ TANDEM AXLE □ ENGINE BRAKE				
	BUX		GD	FR	FR PR UKN				ENT	NTS:								TOOL			
MECHANICAL	_	ENGINE TRANSMISSION CLUTCH		$\boxtimes$				Oil lea										LIFT/TA			
				$\square$			$\square$										$\square$	RAMP LIFT G			
		DIFFERENTIALS		$\boxtimes$																AMERA	
	BRAKES			$\boxtimes$																	
	FRONT REAR I			$\boxtimes$																	
_	BATTE		$\boxtimes$																		
		SERATION						- ادمسيقم	por in hox												
COMMENTS: Mileage unverified. Box structural supports pictured on floor in box.																					
								40.000													

02-13-2023

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107