RTR Services Inc. FORKLIFT						F L			RTR #: 412359 ACCOUNT NUMBER:					1	
CONDITION REPORT					ACCOUNT NAME:										
YEAR: 2		2011			VIN/S	IN/SN: K050348						CAPACI	TY:	5500	
MAKE:		Moffett						EL 🛛 OFF ROAD MODEL							
MODEL:		M55 10'MAST			COL			KTERIOR: RED INTER ON: ☑ YES ☐ NO ☐ N/A • DOOR: ☐ YES ☐							
	ENGINE: TRANS:	KUBOTA HYDROSTA						YES ∐ NO GAS □ F					NO 🗵 N/A		
	HRS:	1,696	110			S IT RUN			- 1	UNI		CAN IT BE D	RIVEN?	☒ '	YES NO UNK
PHYSICAL APPEARANCE															
			GD	FR	PR	N/A	COMM	ENTS							OPTIONS
_	FRONT	FRONT HEAD LIGHTS													PWR STEERING PWR BRAKES
	HOOD TURN SIGNALS GRILL L FRONT FENDER						Dents/	cracked						H	ENCLOSED CAB
						\boxtimes									TINTED GLASS
					+ $=$										AIR CONDITIONER HEATER
	L DOOR														AIR RIDE SEAT
Ճ	L REAR PANEL														AM FM RADIO
вору	SAFETY LIGHTS REAR						Dents/	cracked						\mathbb{H}	TAPE DECK CD PLAYER
	TAIL LIGHTS			\boxtimes											MUD FLAPS
	FRAME TURN SIGNALS			\boxtimes											2WD 4WD
	R FRONT FENDER		-		╁										CUSHION TIRES
	R FRONT DOOR														PNEUMATIC TIRES
	R REAR PANEL WORK LIGHTS														MAST HEIGHT 10' MAX MAST HT
	TOP													\boxtimes	TILT ANGLE
တ္ယ	L FRONT L REAR R FRONT							9.5 SIZE:						\square	FORK LENGTH 48" FORK WIDTH
TIRES							65 % 19.5 SIZE: 65 % 19.5 SIZE:							REACH LIFT	
	R REAR					\boxtimes			SIZE						SIDE SHIFT
တ္က	WINDSHIELD L DOOR		lΗ			\boxtimes								\mathbb{H}	FORK POSITIONERS FORK ROTATOR
REAR WI		WDOW				\square								\boxtimes	PUSH-PULL UNIT
ច	R DOOR MIRRORS														FORK EXTENSIONS HITCH
~	DASH/GUAGES DOOR PANELS SEAT CARPET/MAT CONTROLS		<u> </u>		╁										ROP
RIOR															CHARGER
INTER					\parallel										FRONT STABILISERS
				\boxtimes											
	ENGINE		GD	FR 🖂	PR	UKN	N/A	COMME	NTS:						
MECHANICAL	TRANSM			\boxtimes											
	CLUTCH														
	DIFFERENTIAL 2 ND DIFFERENTIAL						\boxtimes							\exists	
	BRAKES			\boxtimes											
	FRONT END REAR END		$\mid \; \mid \; \mid \; \mid$	\boxtimes										H	
		Y/ELECTR													
COMMENTS: Hours Unverified. Some cosmetic damage on hood and back side. Dents, scratches and rust throughout.															

1/15/25

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.