RTR Services Inc.							: : :: :	: ::	RTR #: 4123699											
BOX TRUCK				(D)		1 1 11 1		ACCOUNT NUMBER:												
CONDITION REPORT					404504				ACCOUNT NAME:											
		2013		_	.ES	434504					PVNE8JT6D4S55037									
MAKE:		Hino		GV		25950 <b>BOX HEI</b>							BOX WIDTH							
MODEL:		268			IEELE	BASE:			COLOR: EXTERIOR: White				INTERIOR: Black							
ENGINE: J08E-VC 7.6L				HP					KEYS: IGNITION:   YES □ NO • DOOR:					_						
TRANS: Auto					GAS 🗵			ANTIFREEZE TESTED:  YES  NO					RATING:							
DOES MOTOR RUN?					□ NO	C	CAN IT BE DRIV				□NO	COLLI	SION DA	MAG	E?	☐ YE	S	⊠ NO		
									AL APPEAR	AN	CE									
BODY	FRONT	BUMPER	GD	FR	PR	N/A	CON	IMENTS							$\square$	PWR S		ONS RING		
	HEAD LIGHTS HOOD				$\boxtimes$										BRA	KES				
							Held	down by	strap, unable to open				⊠ AIR □ HYD							
	TURN SIGNALS GRILL			H										-		PWR L		S		
	D FRONT FENDER				$\boxtimes$										₫	PWR W	IND	ows		
	D DOOR			$\boxtimes$											=	PWR SI				
	D BOX REAR BUMPER				H	+ + -									_			TIONER		
	TAIL LIGHTS			$\boxtimes$											$\boxtimes$		_	EAT D/P		
	P FRONT FENDER			$\boxtimes$											_	AIR RID		USPENSIO	N	
	P FRONT DOOR																	CB? No C	B_	
	P BOX			$\boxtimes$												SLEEP	_		_	
TIRES	TOP D FRONT					+ = -	15/3	2 % 295/7	5R 22.5 SIZ	'F·					_	TRANS		ENT ROOF	-	
	D REAR A1 (S/D?)								295/75R 22		SIZE:				=	BOX DO				
	D REAR A2 (S/D?)						4/00	%	SIZE:	_					_	SIDE D				
	_	P FRONT P REAR A1 (S/D?)							R 22.5 SIZE 295/75R 22.		IZF·					L TANK □ SING		GAL		
	P REAR A2 (S/D?)					$\boxtimes$	0,02	%	SIZE:							□ DUA	L G	۸L	_	
	SPARE WINDSHIELD			<u> </u>			Dool	%	SIZE:						_	MUD FI	_APS	3		
LASS	D FRONT DOOR						ROCI	chips in	window					-		ELS □ ALU	MIN	UM		
	REAR WINDOW P FRONT DOOR MIRRORS			$\boxtimes$								STEEL ☐ BUD ☐ SPOKE								
G																				
	DASH	110			$\boxtimes$									1		EXHAU		6/D? <u>S</u>		
S.		PANELS									;	SUSPENSION								
INTERIO	SEAT(S) FLOORING			$\boxtimes$			Driver seat has tear Rust and tears					☐ AIR ⊠ SPR	ING							
	HEADLINER						rtuot	una toure									)			
=	SLEEPER						Uala	on floor	of how Moo	٦.	hinning o	II araund			=	TANDE				
ВОХ			GD	FR	PR	UKN	N/A	COMM	of box, Wood Chipping all around IENTS:					_	ENGINI Tool e					
MECHANICAL	ENGINE			$\boxtimes$												LIFT/TA				
		TRANSMISSION CLUTCH		$\square$											=	RAMP LIFT G	۸TE			
	DIFFERENTIALS			$\boxtimes$												LII 1 G/	\!L			
	BRAKES			$\boxtimes$																
	FRONT END REAR END			$\boxtimes$										_						
	BATTERY/ELECTR														ă					
-		ERATION	(orific -l	1 ;44		onerst'	Dom	000 00 50	ant of tree-	0"	l interier		and lat-	ria-		o ho::				
COMMENTS: Miliage Unverified. Lift gate is operable. Damage on front of truck and interior of the cab and interior of the box.																				
1/27/2025																				
		EMPLOYEE'S FUL	L NAME (F	LEASE	PRINT	<u>)</u>		DATE				EI	MPLOYEE'S	SIGN	ATUR	E				
	_						formation		hin this report to	be tr	ue and accura									