RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	4073446
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2020				
MAKE:	Vermeer	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	SC362	☐ OPERATIONAL			
SN:	1VRF112YXM100408	☒ NON OPERATIONAL			
POWER:	Vangaurd 35	☐ UNTESTABLE			
DESCRIPTION:	Stump grinder				
SHOT / COUNT / HOUR: 642					
NOTES / COMMENTS: Hours unverified. Local shop found the engine is locking up due to a broken connecting rod, one piston not moving in bore when rolling engine over. The battery looks old and tests bad, battery cables are very corroded. Fuel lines are old, weathered and brittle. Door hinge bracket is busted. The engine, battery, battery cables, fuel lines and door hinge bracket all need to be replaced. This work is estimated to cost around $4,700.					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
	7/31/2024	

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107