	RTR Serv	vices Inc.								RTR #: 403308						0-03			
PICK-UP TRUCK				ſ						ACCOUNT NUMBER:									
CONDITION REPORT YEAR: 2011			V	IN:			AEI OB	DB036	ACCOUNT NAME:				MILES:	S: 234.983					
MAKE: Ford					ICENS	F·	1FDXE4FL9BDB0			STATE				TAGS:		- ,			
MODEL: F450				AB TY		Standard Co						White		INTERIOR:		Gray			
ENGINE: V-8 5.4L			_			N: ⊠ YES □ NO · DOOR: ⊠ YES □ NO									,				
TRANS: Automatic			F	UEL:	⊠ GAS	☐ DIESEL ☐ HYBRID ANTIFREEZE TESTED: ☐ YES							S 🔲 N	O RATI	NG				
DOES MOTOR RUN? YES			S	⊠ NO	С	AN IT BE DRIVEN			? ☐ YES ☒ NO COLLISION DAMA					/IAGE	? \ \ \ \ \ \ \	s 🗵	NO		
PHYSICAL APPEARANCE																			
	FRONT B	GD	FR	PR 🖂	N/A	Missi		MENTS							OPTIONS PWR STEERING				
	HEAD LIGHTS HOOD TURN SIGNALS			\boxtimes			IVIIOSI	iig								_		G	
															┦믐		OCKS INDOW	c	
	GRILL														╛╏		_	3	
BODY][\boxtimes													ER SEA'	_	
															$\dashv \exists$		E CONTI	-	
	CARGO BED REAR BUMPER TAIL LIGHTS][$\exists \; \exists$		HEEL GLASS		
															$\dashv \boxtimes$		NDITIO		
	TAIL GATE TAIL PIPE														\dashv		M WHE	ELS	
	P FRONT FENDER				$\overline{\boxtimes}$										$-\mid \square \boxtimes$		_		
	P DOOR P REAR FENDER														$\exists \; \exists$		-		
	TOP														$\exists \exists$	-	M WHE	ELS	
	D FRONT D REAR P FRONT]						R/16 S						$\exists \ \Box$		A C K A C I	_	
RES															$-\mid \boxtimes \boxtimes$				
F	P REAR SPARE								OR/16 S	SIZE:							ING		
GLASS	WINDSHIELD						%)	SIZE:										
	_	D FRONT DOOR		\boxtimes															
	D REAR PANEL P FRONT DOOR P REAR PANEL REAR WINDOW DASH DOOR PANELS SEAT(S) CARPET HEADLINER				\parallel										$\exists \exists$				
				\boxtimes															
RIOR																			
NTE															┨				
=				\boxtimes			N1/A	0011											
	ENGINE		GD	FR 🖂	PR	UKN	N/A	COM	MENTS): 									
ECHANICAL	_	TRANSMISSION		\boxtimes															
	CLUTCH BRAKES FRONT END																		
				\boxtimes															
Ξ	REAR END						\parallel	Need	ds batte	ery									
COMMENTS: Mileage unverified. Engine will not turn over. Leaking oil. Missing front bumper assemblies.																			
							_	1/0.4/2	00.4										
	EMI	PLOYEE'S FUL	I NAME (DI EVE	DDINIT'		04	1/04/20			_		EM	PLOYEE'S	SIGNAT	UPE			
							formation of			report to	be tru	e and accura	te to the best						