RTR Services Inc.						- 15 m	- J.)			RTR #: 406193					5			
EXCAVATOR								ACCOUNT NUMBER:										
WHEEL/TRACK								ACCOUNT NAME:										
CONDITION REPORT																		
	YEAR:	2012			VIN/S	N:	HCM1YA	00E002	68838									
	MAKE:	Hitachi			□ WHEEL ☑ TRACK													
	MODEL:	ZX35U-3			COLOR: EXTERIOR:				Orange / Black INTERIOR: Gr									
	ENGINE:	GINE: Yanmar 3KNPA			KEYS: IGNITION: ⊠ YES				ES □ NO □ N/A · DOOR: ⊠ YES □ NO □ N/A									
TRANS		Hyd			FUEL	: 🛛 D	IESEL 🗌	GAS	ANT	ANTIFREEZE TESTED: ☐ YES ☒ NO				RATING:				
HRS:		2,760				IT RUN			NO UNK CAN IT BE D			DRIVEN2	M	YES	Пио			
PHYSICAL APPEARANCE																		
				GD FR		N/A	COMM	ENTS								OPTIONS		
	FRONT P			PR		COMIN	LIVIS								LOSED CA	В		
	HEAD LIGHTS														_	ED GLASS		
	HOOD TURN SIGNALS GRILL													\boxtimes		CONDITION	IER	
														\square	HEAT			
-					<u> </u>											RIDE SEAT		
	L FRONT PANEL L DOOR L REAR PANEL			$\boxtimes \boxtimes$												M RADIO E DECK		
_														1 🗄		LAYER		
ВОД		SAFETY LIGHTS			ΙĦ										BUC			
В		REAR PANEL														K COUPLE	R	
		TAIL LIGHTS				\boxtimes								\square		THUMB		
	FRAME			\boxtimes												CK WIDTH	_	
	TURN SIGNALS R FRONT PANEL		$\vdash \vdash \vdash$		<u> </u>										ROP			
	_	R FRONT DOOR		\boxtimes											BLAI	DE		
	R REAR PANEL													1 🗄				
	WORK LIGHTS			\boxtimes														
	TOP			\boxtimes														
TIRES	L FRONT					\boxtimes		%	SIZI									
	L REAR (S/D?) R FRONT							%	SIZI SIZI									
	R REAR (S/D?)				\parallel			<u>%</u> %	SIZI									
	TRACKS		lΗ				20%	70	0121									
	WINDSHI		\boxtimes															
SS	L DOOR			\boxtimes														
GLAS		REAR WINDOW																
ര		R DOOR																
	MIRRORS DASH/GUAGES				+ $=$ $-$									┧╏				
RIOR		DOOR PANELS												1 🗇				
I SEAT				\boxtimes														
INTER		ARPET/MAT		\boxtimes														
CONTROLS			GD	FR			21/2	00111										
	ENGINE	ENGINE			PR	UKN	N/A	COMMENTS: Hydraulic fluid seal leak at the piston bucket end										
_		TRANSMISSION DIFFERENTIAL UNDERCARRIAGE					18	riyura	auno mu	nu scai le	un al	me hisioii	DUCKEL EIIU					
MECHANICAL				\boxtimes														
Ζ				\boxtimes								-					•	
ਜ਼ੋ		BRAKES																
ΜĔ		FRONT END																
_		REAR END BATTERY/ELECTR			H	l H	ΙH											
COMMENTS: Hours unverified. Unit is reported to have an ignition misfire and AC stops cooling after a priod of time. Areas of rust.																		
	-						7/18	3/2024				-	-			-		
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE																		
						rtify all info	ormation cont		in this repo	ort to be true	and acc		st of my knowled					