RTR Services Inc. TRACTOR									RTR #: 408310 ACCOUNT NUMBER:					1			
CONDITION REPORT						0	0		ACCOUNT NAME:								
YEAR: 1995				VIN/SN: Unknown-Illegible (client approved)													
MAKE: Ford																	
MODEL: 8770				COLC		EXTERIOR: Blue INTERIOR:							Gray				
ENGINE:																	
TRANS:				-	_		EL 🗌 GAS 🔰 ANTIFREEZE TESTED: 🗌 YES 🖾 NO						RATING:				
HRS: 1,536					DOES	IT RUN		□ YES ☑ NO □ UNK CAN IT BE DRIVEN' PHYSICAL APPEARANCE				RIVEN?					
_			GD	FR						ANCE							
	FRONT	FRONT			PR	N/A	COMN	IENTS								OPTIONS	
	HEAD LIGHTS			\boxtimes												ED GLAS	
	HOOD			\boxtimes										\boxtimes	AIR C	CONDITIC	ONER
	TURN SIGNALS			\boxtimes											HEAT		-
BODY	GRILL L FRONT PANEL													\boxtimes		RIDE SEA	
	L DOOR			\boxtimes												E DECK	,
	L REAR PANEL			\boxtimes												LAYER	
	WORK LIGHTS															STEERIN	-
	REAR TAIL LIGHTS			\boxtimes											PWR 2WD	BRAKES	6
	FRAME			\boxtimes										\boxtimes	4WD		
	R FRONT PANEL			\boxtimes										\boxtimes	PTO		
	R FRONT DOOR			\boxtimes										\boxtimes			H
	R REAR PANEL SAFETY LIGHTS			\boxtimes											ROP		VD
	TOP			\boxtimes											AUNI		
TIRES	L FRONT			\boxtimes					x85R28 SI	ZE:							
	L REAR (S/D?)								R22 SIZE:								
Ē	R FRONT R REAR (S/D?)			\boxtimes					x85R28 SI R22 SIZE:	ZE:							
	WINDSHIELD							/0 104									
SS	L DOOR			\boxtimes													
GLA:		EAR WINDOW															
G		R DOOR MIRRORS															
	DASH/GUAGES																
R	DOOR PANELS			\boxtimes													
RIC	SEAT			\boxtimes													
NTERIOR	ELECTRICAL CARPET/MAT				\square												
-	CONTROLS				\square												
			GD	FR	PR	UKN	N/A	COM	IMENTS:								
MECHANICAL	ENGINE TRANSMISSION																
		CLUTCH				\boxtimes											
	DIFFERENTIAL					\boxtimes											
		2 ND DIFFERENTIAL					\boxtimes										
	BRAKES																
	FRONT END REAR END																
	BATTERY/ELECTR							Repl	aced 10/20	24							
COMMENTS: TT Tori/Barry at yard-ignition switch and batteries have been replaced. Coolant added. Unit cranks but won't start. Sounds as if it's not even trying to start and could be related to what the lessee had advised: believes the oil pump is bad and it's tied into the fuel system. Asked if it needed fuel. Barry said the unit has fuel and adding more would just be throwing good money after bad. Barry's not very familiar with tractors.													system.				

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107