RTR Services Inc. TRAILER CONDITION REPORT										RTR #: 312 ACCOUNT NUMBER: ACCOUNT NAME:					3177-	02			
<b>YEAR:</b> 2012			BODY	TYPE:	Dry van						D1CL558510								
MAKE:		Wabash			LICENSE:					STATE:		TAGS: MN:		N:	YR:				
MODEL:		DVCVHPC			COLOR:		EXTERIOR:		Wł	White			INTERIOR:		R: \	White / Aluminum			
LENGTH: 53'				WIDTH:					HEIGHT:						<b>GVW:</b> 68,000				
			□ P	INTLE	□ 5™				7/8" BALL 🗌 2" BALL										
IS IT ROAD READY? 🛛 YES				S			COLLISION DAMA					10	D KEYS		🗌 YES 🛛 🖾		NO 🛛		
_									API	PEARANO	E								
BODY	FRONT	PANEL	GD	FR	PR	N/A	COMN	IENTS					ľ	$\boxtimes$	OPTIONS AIR RIDE SUSPENSION				
	нітсн			$\boxtimes$									SPRING SUSPENSION						
		D SIDE PANEL SIDE DOOR (S) REAR PANEL		$\boxtimes$		$\square$							_	<ul> <li>☑ AIR BRAKES</li> <li>☑ ELECTRICAL BRAKES</li> <li>☑ HYD BRAKES</li> </ul>					
	RFAR I			$\square$															
		REAR DOOR (S)		$\boxtimes$												$\boxtimes$	SLIDER A		
	P SIDE PANEL		$\boxtimes$												WH	EELS			
	REAR BUMPER			$\boxtimes$														=	
IOR	FLOOF	FLOOR 🗌		$\boxtimes$															
	D SIDE	D SIDE PANELS		$\boxtimes$											r		⊠ ALUMI LIFT/TAG		
NTERIO		P SIDE PANEL		$\boxtimes$													SPARE TI		<b>(</b>
	CARGO RAILS			$\boxtimes$													REFIGER	ATION UI	TIN
	CEILING  D FRONT					%	SIZE:									REEFER I		-	
TIRES		D REAR A1 (S/D?)			$\boxtimes$		%	-	295/	75R22.5							MUD FLA		
	D REA	D REAR A2 (S/D?)			$\square$		%		295/	75R22.5					[		ROLL UP		DOR
		D REAR A3 (S/D?) P FRONT				$\boxtimes$	%	SIZE: SIZE:									LOADING		
	P REAL	P REAR A1 (S/D?)			$\bowtie$		%		295/	75R22.5							BATTERT		
		P REAR A2 (S/D?)						% SIZE: 295/75R22.5											
	P REAR A3 (S/D?) SPARE					$\boxtimes$	%	SIZE: SIZE:											
			GD	FR	PR	UKN	N/A	COMMI	ENTS	S:									
lICAL		TAIL LIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR AIR HOSE/GLAD		$\mathbb{Z}$		H									L				
	CLEAR																		
AAA	SLIDEF																		
EC															L				
Σ	AIR HC																		
	ELECTR PIGTAIL														[				
COMMENTS: 2 axles. Scratches and dents all over unit.																			
Vector       SIGNAL LIGHTS       I																			

12/22/2023

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107