RTR Services Inc. TRAILER CONDITION REPORT										RTR #: 3123177-03 ACCOUNT NUMBER: ACCOUNT NAME:						
YEAR: 2012				BODY TYPE:			an		VIN#: 1JJV53D7CL558673			8673				
MAKE: Wabash				LICENSE:					STATE:		TA	TAGS: MN:		YR:		
MODEL: DVCVHPC				С	COLOR:		EXTERIOR: W		hite		IN	INTERIOR:		White / Aluminum		
LENGTH: 53'		53'			WIDTH:				Н	HEIGHT:					GVW : 68,000	
HITCH: GOOSE NEC		ECK	☐ PI	☐ PINTLE ☐ 5 TH		WHEEL PIN 17] 1 7/8" I	7/8" BALL 🔲 2" BALL		L 🗆	☐ 2 5/16" BA		ALL		
IS IT ROAD READY? ☐ YES					□ №			LISION DA			S 🛛	NO	KEYS	3 :	☐ YES	⊠ NO
							F	PHYSICAL	APPEA	RANCE						
	EDON'T DANE:		GD	FR	PR	N/A	COM	MENTS							OPTIONS	
ВОДУ	HITCH D SIDE SIDE D REAR I REAR I P SIDE	NT PANEL H DE PANEL DOOR (S) R PANEL R DOOR (S) DE PANEL R BUMPER													 □ SPRING SUSPENSION □ AIR BRAKES □ ELECTRICAL BRAKES □ HYD BRAKES 	
INTERIOR	FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING														STEEL ALUMI LIFT/TAG SPARE TI REFIGER REEFER I	NUM AXLE RE RACK ATION UNIT
TIRES	D REAI D REAI P FROI P REAI P REAI	R A1 (S/D?) R A2 (S/D?) R A3 (S/D?) NT R A1 (S/D?) R A2 (S/D?) R A3 (S/D?)					% % % % % %	SIZE: SIZE: SIZE:	295/75R 295/75R	22.5					TOOL BO MUD FLA ROLL UP LOADING BATTERY	PS REAR DOOR RAMP
	_		GD	FR	PR	UKN	N/A	COMM								
CLEAF SLIDE REFRI LANDI AIR HO		GHTS L LIGHTS ANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL														
СО	COMMENTS: 2 axles. Scratches and dents all over unit.															
		EMPLOYEE'S FULI	NAME (PLEASI	E PRINT)		12	2/22/2023 DATE	3			EM	PLOYEE'S SIG	GNATU	IRE	