RTR Services Inc. TRAILER CONDITION REPORT											RTR #: 3124362 ACCOUNT NUMBER: ACCOUNT NAME:								
YEAR: 2005				BODY	TYPE:	Dry Van			VIN#: 1JJV532W25L871716					71716					
		Wabash			LICENSE:					STATE:					S: MN:			YR:	
MODEL: Semi				COLOR:		EXTERIOR: W		WI	hite			INTERIOR		TERIOR:	Steel/Wood				
		53'		v		WIDTH:	102"			HE	IGHT:	13'6"				GVW : 68,000		3,000	
		☐ GOOSE N	ECK	□Р	I] PINTLE ⊠ 5 TH		WHEEL PIN		17	7/8" BALL		□ 2"	☐ 2" BALL ☐ 2 5/16" BA		ALL	 \LL			
IS IT ROAD READY? 🛛 YES			s	□ NO		COLLISION DAMA			GE?	E? ☐ YES ☐ NO		KEYS	3:	☐ YES	⊠ NO				
PHYSICAL APPEARANCE																			
GD			FR	PR	N/A	COM	MENTS	ENTS							OPTIONS				
TIRES INTERIOR BODY	REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?)						% % 40 % 40 % % % 40 % 40	SIZE: SIZE: SIZE:	ips							AIR BRA ELECTF HYD BR SLIDER BUD SPO STEI ALU LIFT/TA SPARE REFIGE REEFEI TOOL B MUD FL ROLL U LOADIN	SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE		
							% SIZE:												
MECHANICAL	CLEAR SLIDER REFRIC LANDII AIR HO	GHTS L LIGHTS ANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL	GD		PR		N/A	Leak	ENT	S:									
COMMENTS: Black soot present around the bottom of the trailer on the exterior.																			
01/04/2024																			
		EMPLOYEE'S FULL By sig					ormation o	DATE ontained withi	n this	report to	be true a	and acc	curate to th		PLOYEE'S SI of my knowled				