RTR Services Inc.						A	n I			RTR #: 3043222						2			
HEAVY TRUCK									ACCOUNT NUMBER:										
CONDITION REPORT					ا				ACCOUNT NAME:										
YEAR:		2017			MILES		20		VIN#:		3HS	HSDJAPR9HN429575							
MAKE:		International		GV	GVW : 52,35		LICENSE:					ST: TAGS:		MONTH			YR:		
MODEL:		Prostar+122 6x4		W	WHEELBASE:				С	COLOR:		EXTERIOR: Silver		,	INTER	OR: Gray			
ENGINE:		Cummins ISX15 14		HP	HP		BODY TYPE:		Sleeper		P	KEYS: IGNITION: X YES		N: ⊠ YES	□ NO	• DO	DOOR: ⊠ YES □ NO		
TRANS:		10 Speed Manual		FU	FUEL: 🗌 🤇		AS 🛛 DIESEL		ANTIFREEZE		TEST	TESTED: 🗌 YES 🖾 NO		NO	RATIN	G: N/A		Ά	
DOES M		OTOR RUN?	⊠ YE	S	□ NO	1	CAN IT B							ISION DA	MAGE?	□ Y	□ YES 🛛 🖾 I		0
								PHYSIC	AL AF	PPEARAN	NCE								
ВОДУ			GD	FR			COM	MENTS									OPTI		
	FRONT BUMPER HEAD LIGHTS HOOD															PWR	STEE	ERING	
													_ BRA	KES ⊠ AII	R				
	TURN SIGNALS			\boxtimes												⊟нү			
	GRILL															PWR			
	D FRONT FENDER D DOOR			$\boxtimes \boxtimes$												PWR		OWS	
	D SLEEPER				lΗ	lΗ									$\dashv $	PWR			
	REAR BUMPER			\boxtimes														ITIONI	
				\boxtimes											$\dashv \square$			SEATI	D/P :NSION
	P FRONT FENDER		H		Н										┛	CONV			
	P FRONT DOOR			\boxtimes												SLIDI			EEL
	P SLEEPER			\boxtimes												AM FI			CD
TIRES	TOP D FRONT						60 %	295/75	R22.5	SIZE:						TAPE SLEE			
	D REAR A1 (S/D?)			\boxtimes			60 %	295/75	R22.5	SIZE:					\square	ELEC	TRIC	AL PI	
	D REAR A2 (S/D?)				\boxtimes			295/75								GLAD		NDS	
	P FRONT P REAR A1 (S/D?)			\boxtimes				295/75 295/75							FUE	L TAN		GAL	
	P REAR A2 (S/D?)							295/75										SAL_	
	SPARE							%	S	IZE:						MUD	FLAF	S	<u>.</u>
S	WINDSHIELD D FRONT DOOR			\boxtimes											WHE	EELS AL	LIMIE	II IM	
S	REAR WINDOW				lΗ													4OIVI	
REAR で P FRO MIRRO DASH		IT DOOR		\boxtimes												☐ BU			
		RS												\dashv_{\bowtie}	☐ SP EXHA				
~	DOOR PANELS SEAT(S)				\parallel											PENS		3/0:	_
RIO				\boxtimes									⊠ All						
INTER	CARPET																	•	
=	HEADLINER SLEEPER			\boxtimes											\dashv_{\boxtimes}	☐ PA		XLE	
			GD	FR	PR	UKN	I N/A	COMI							\square	ENGII	NE B	RAKE	
MECHANICAL	ENGINE							Oil S	pewin	g out of	the e	engine			$\exists \exists \Box$	TOOL	_		
	TRANSMISSION CLUTCH														$\dashv \exists$	LIFT/1		AXLE	
	DIFFERENTIALS														一				
	BRAKES																		
	FRONT END REAR END			\boxtimes											$\exists \exists$				
		BATTERY/ELECTR			lН		New bat			tteries 08/2023					ᅱ旹	1 🖯			
COMMENTS: Mileage unverified. Missing a rear tire on the passenger outside 2 nd axle. Missing exhaust manifold, alternator, and turbo. Unit is													Unit is						
not	reccom	nended to be	ran ver	y Iong	j.														
							05	5-26-20	023										
		EMPLOYEE'S FULI By siç					information of	DAT contained w		is report to be	e true a	and accurat		MPLOYEE'S at of my know					_