RTR Services Inc.									RTR #: 305321						19	9			
BOX TRUCK CONDITION REPORT				(I)		1 1 11 1			ACCOUNT NUMBER:										
		2015	KI	NAII	ES .	424 402			VIN#: 3ALACWDT4FDGD4479										
				_		434,493		OX HEIGH						BOX WIDTH 8'6"					
		Freightliner M2 106		GVW:		26,000		JX NEIGN		COLOR: EXTERIOR:		White		BOX WIDTH 8					
MODEL: ENGINE:		Cummins 6.7				ASE:			KEYS: IGNITION: X YES 1										
TRANS:		Automatic		HP		 │ GAS ⊠ DIESEL		+		TED: YES NO				RATING:					
DOES MOTOR R		*****	⊠ YE	<u> </u>	□ NO			BE DRIVE				COLLISION DAM					 ES │ □ NO		
BOLO MOTOR ROW:			J [ANTIL		AL APPEAR			COL	LIGIOI	I DAI	IAGE:	''	.5			
			GD	FR	PR	N/A	COM	MENTS									OPTIO	ONS	
ВОДУ	_	BUMPER																	
	HEAD	LIGHTS												BRA	BRAKES ⊠ AIR				
	TURN	TURN SIGNALS GRILL D FRONT FENDER		\boxtimes											☐ HYD				
				\boxtimes											- =	PWR WINDOWS			
	D DOOR			\boxtimes															
	DBOX	D BOX			무											PWR N		_	
	REAR BUMPER TAIL LIGHTS			\boxtimes											$\perp \boxtimes$			TIONER EAT D/P	
	REAR	PANEL																	
	_	NT FENDER NT DOOR														AM FM RADIO TAPE / CD / CB? <u>CD</u>			
	P BOX			\boxtimes												SLEEP	ER S	IZE?	
	TOP D FRONT			\boxtimes			50.0	50 % 11R 22.5 SIZE:					TRANSLUCENT ROOF E-TRACK LINING			F			
TIRES		D REAR A1 (S/D?)		\boxtimes				6 11R 22.5									_	LIGHT	
	DREA	D REAR A2 (S/D?)					50.0		SIZE:							SIDE D			
	PREA	P FRONT P REAR A1 (S/D?)		\boxtimes				6 11R 22.5 6 11R 22.5								L TANK □ SIN		GAL	
	P REAR A2 (S/D?)					\boxtimes	%	% SIZE:				DUAL GAL							
		SPARE WINDSHIELD		<u> </u>	\Box		9	<u>6</u> S	SIZE:							MUD F	LAPS	5	
GLASS	D EDO	D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS																UM	
	REAR																		
Ĺ	MIRRO																		
	DASH DOOR PANELS															EXHAL PENSIO		5/D?	-
OR	SEAT	SEAT(S) FLOORING HEADLINER SLEEPER BOX														⊠ AIR			
	FLOOF																		
1	SLEEP														\dashv	☐ PAI TANDE		KLE	
<u> </u>							21/4	001111	ENTO							ENGIN	E BR	AKE	
MECHANICAL	ENGIN	GD	FR ⊠	PR	UKN	N/A	СОММ	ENIS:							TOOL				
		TRANSMISSION														RAMP			
	CLUTC	CLUTCH DIFFERENTIALS		\square											$\exists \Box$	LIFT G	ΑГΕ		
	BRAKE	BRAKES		\boxtimes															
		FRONT END REAR END		\boxtimes											$\exists \exists$				
ֹ	BATTERY/ELECTR														╛╏				
Ļ		GERATION	(orifical	1h a "	lac:		\boxtimes	folling	2014 cm d !=	loo!:-	a beer	0 Th-	0025	on 4l-		ام مديا	a h	, are semi-	n.a.
COMMENTS: Mileage unverified. the floor insdie the box is falling apart and is missing boards. The screw on the outside of the box are coming out. There is dents in the side of the box on both sides.												ııy							
L																			
	08/12/2023																		
		EMPLOYEE'S FUL					_	DATE	<u> </u>		and	la te il ·			SIGNATUR				
		By Si	gnature abo	200 TAN	nereby	centry all it	iiioimation	contained wit	hin this report to I	e (rue	anu accura	ie io tne b	est of m	y knowle	uge at pre	sent.			