RTR Services Inc. BOX TRUCK CONDITION REPORT		RTR #:	3053529
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2009	MILES	296,755			VIN#:	2FZACFBS49AAH1671		
MAKE:	Sterling	GVW:		BOX HEIGHT	90"	BOX LENGTH	26'	BOX WIDTH	92"
MODEL:	Acterra	WHEELBASE:		COLOR: EXTERIOR:	White	INTERIOR:	Tan		
ENGINE:		HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Manual	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO				RATING:	
DOES MOTOR RUN?	☒ YES	☐ NO	CAN IT BE DRIVEN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO	

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D BOX	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P BOX	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☐	☒	☐	25 % 275/80R/22.5 SIZE:
	D REAR A1 (S/D?)	☐	☐	☒	☐	0 % 275/80R/22.5 SIZE:
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	P FRONT	☐	☐	☒	☐	25 % 275/80R/22.5 SIZE:
	P REAR A1 (S/D?)	☐	☐	☒	☐	0 % 275/80R/22.5 SIZE:
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	Crack
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	FLOORING	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☐	☐	☒	
	BOX	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☒	☐	☐	☐	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	
	REFRIGERATION	☐	☐	☐	☐	☒	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☒ AIR
  - ☐ HYD
- ☒ PWR LOCKS
- ☒ PWR WINDOWS
- ☒ PWR SEATS
- ☐ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☐ AIR RIDE SEAT D/P _____
- ☒ AIR RIDE SUSPENSION
- ☒ AM FM RADIO
- ☐ TAPE / CD / CB? _____
- ☐ SLEEPER SIZE? _____
- ☐ TRANSLUCENT ROOF
- ☐ E-TRACK LINING
- ☒ BOX DOME LIGHT
- ☐ SIDE DOOR
- FUEL TANKS
  - ☒ SINGLE GAL 100
  - ☐ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☐ ALUMINUM
  - ☒ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☒ EXHAUST S/D? S
- SUSPENSION
  - ☒ AIR
  - ☐ SPRING
  - ☐ PAD
- ☐ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX _____
- ☐ LIFT/TAG AXLE
- ☐ RAMP
- ☒ LIFT GATE
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

COMMENTS: Mileage unverified. Missing passenger steps.

05/25/2023

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107