RTR Services Inc. BOX TRUCK						1			RTR #: 305478 ACCOUNT NUMBER:					781	31			
CONDITION REPORT																		
		2018		MILES		472,109			VIN#: 1HTMMMML9JH435459									
MAKE:		International	national		GVW : 25,		99 BOX HEI		85	BOX LE	NGTH	GTH 26		BOX WIDTH				
MODEL:		4300		_	WHEELBASE:		272			EXTERIOR			INTERIOR:			Bray		
ENGINE:		Cummins ISB	HP 240					EYS: IGNITION: YES NO · DOOR: D										
TRANS:		Automatic	⊠ YE			GAS				EZE TESTED: ☐ YES ☒ NO YES ☒ NO COLLISION [RATIN			NO.		
DOES MOTOR RUN? X YES					_ NO		ANIIE	BE DRIVEN PHYSICA	AL APPEARANCE					MAGE?	☐ YI	:5	⊠ NO	
		GD			PR	N/A	CON	IMENTS						OPTI	ONS			
ВОДУ	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS GRILL			\boxtimes											☐ PWR STEERING BRAKES			
				\boxtimes									BK	⊠ AIR				
				\boxtimes											☐ HYI		e	
			H	\boxtimes											PWR V			
				\boxtimes										$\dashv \exists$	PWR S			
	REAR BUMPER			\boxtimes													TIONER	
	TAIL LIGHTS			\boxtimes										$\dashv \exists$			EAT D/P USPENSION	
	P FRONT FENDER			\boxtimes	╽										AM FM	RAD	OIO	
	P FRONT DOOR DOOR						Scra	ne damage	on the ria	ht side of bo	nx .			┦뭄				
	ТОР			\boxtimes				Scrape damage on the right side of box				☐ TRANSLUCENT ROOF						
TIRES				\boxtimes				10 % 295/75R22.5 SIZE: 20/40 % 295/75R22.5 SIZE:							☑ E-TRACK LINING☑ BOX DOME LIGHT			
	D REAR A2 (S/D?)					\boxtimes		% SIZE:							SIDE DOOR			
	P FRONT P REAR A1 (S/D?)			\boxtimes				10 % 295/75R22.5 SIZE: 20/40 % 295/75R22.5 SIZE:							_ FUEL TANKS ☐ SINGLE GAL			
	P REAR A2 (S/D?)					\boxtimes		% SIZE:							☑ DUAL GAL			
GLASS	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR MIRRORS				\Box			% SIZE:					☐ MUD FLAPS ☐ WHEELS ☐ ALUMINUM ☐ STEEL					
				\boxtimes														
				\boxtimes							□ BUD							
							Arm	s of large s	ide mirrors	damaged				\dashv_{\sqcap}	☐ SPO		s/D2	
RIOR	DOOR PANELS SEAT(S) FLOORING HEADLINER											SUSPENSION						
															☐ AIR			
INTERI																		
_	SLEEPER BOX													$ \parallel$	TANDE ENGIN			
		GD	FR	PR	UKN	N/A	COMME	ENTS:				TOOL	вох					
اد	ENGINE TRANSMISSION			\square			\parallel	Transm	ission Oil F	ilter Error S	Showing	g on	Dash	$\exists \exists$	LIFT/T	AG A	ALE	
MECHANICAL		CLUTCH DIFFERENTIALS BRAKES						Drive S	o Chaff is Damanad			LIFT G	ATE					
								Dilve 3	Shaft is Removed			$\exists \exists$						
	FRONT END			\boxtimes										$\exists \exists$				
_	REAR END				╽╘													
REFRIGERATION																		
		- · J - ·····																
							-	0.00.55=										
		EMPLOYEE'S FUL	I NAME (B	I FASE	DDINIT	<u> </u>	_0	6-06-202	3			EME	I OVEE'S	SIGNATU	DE			
							nformation		in this report to	be true and accu	rate to the							