RTR Services Inc.												RTR #: 306143						4				
<b>HEAVY TRUCK</b>												ACCOUNT NUMBER:										
	CONDI	TION REPO	RT		ACCOUNT NAME:										8							
YEAR:		2014		MI	LES	619,7	619,774				VIN#: 3HSDJSNR7EN779050											
MAKE:		International		G۱	<b>GVW</b> : 52,35			LICEN	ISE:				ST:		TAGS:	MON	TH		YR:			
MODEL:		Prostar		WI	WHEELBASE:					COLOR: E		EX	XTERIOR: Red			INTE	RIO	R:	Gray			
ENGINE:		N13			•		BODY TYP			Co	onventional KEYS: IGNITION: X					S □ NO • DOOR: ⊠ YES □ NO						
TRANS:		10 Speed	FU	EL:	GAS	⊠ DIESEL A			AN	NTIFREEZE TESTED: ☐ YES ⊠ NO				NO	RATING:							
DOES N		OTOR RUN?	RUN? XES		□ NO	) C/		AN IT BE DR		RIVEN? XES		3	□ NO COLLISION D		ISION DA	MAGE?		☐ YES ⊠ NO		10		
								PHYSICAL			APPEARANCE											
			GD	FR	PR	N/A	١.	COM	<b>MENTS</b>									OPT	IONS			
	_	BUMPER																WR STE	ERING			
	HEAD	LIGHTS					ŀ	-						BR		AKES ⊠ AIR						
	TURN SIGNALS						-									$\dashv$	☐ HYD					
	GRILL															P	WR LOC	_				
<b>-</b>	D FROI					ļ	Paint	Chips							$\dashv \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	-	WR WIN					
BODY	D DOOR						-									$\dashv \square$		WR SEA WR MIR	_			
	REAR BUMPER																	AIR CONI		ER		
	TAIL LIGHTS					Į											IR RIDE	-				
	REAR PANEL   P FRONT FENDER															$-\mid \boxtimes$		AIR RIDE CONV. 5 <sup>TI</sup>				
		P FRONT DOOR					f									$\exists \exists$		SLIDING				
	P SLEEPER															$\square \boxtimes$		M FM R				
-	TOP							40 %		SIZ	7F ·							APE / CI				
	D REAR A1 (S/D?)						f	40 %		SIZ						$\dashv                   $		LECTRI				
ပ္သ	D REAR A2 (S/D?)						Ī	40 %		SIZ	ĽE:							SLAD HA	NDS			
TIRES	P FRONT P REAR A1 (S/D?)						ļ	40 %		SIZ						FU		TANKS	- CAI			
							ŀ	40 % 40 %		SIZ						$\dashv$		⊒ SINGL ☑ DUAL		00		
	SPARE								%		SIZE:						N	IUD FLA				
S	WINDS					ļ	1 rock	chip.							Wi		ELS					
GLASS	D FRONT DOOR REAR WINDOW						ŀ									-	_	☑ ALUMI □ STEEL				
ଧ	P FRONT DOOR																_	BUD	-			
	MIRRORS		_=														_	SPOK		_		
<u>~</u>	DASH					ļ											EXHAUST ENSION	S/D?	<u>s</u>			
RIOR	DOOR PANELS SEAT(S)		H				ŀ									_ 30	_	Z AIR				
NTEF	CARPET			$\boxtimes$			[										_	SPRIN	G			
Z	HEADLINER				<del>                                      </del>		ļ									$\perp$	_	PAD	AVI =			
-	SLEEPER GE			⊠ FR	PR	UKI	N	N/A	COM	ME	NTS:					$\dashv \boxtimes$		ANDEM				
	ENGIN														╗┇	Т	OOL BO	Χ				
ECHANICAL	TRANSMISSION								11	<b>v</b> -	dal					ᆜ 🛭		IFT/TAG	AXLE			
	CLUTCH DIFFERENTIALS								Hard	peo	aaı.					$\dashv \exists$	٧	VET KIT				
H	BRAKES															ᅥᆸ						
ME	FRONT END		_																			
	REAR END							│														
COMMENTS: Mileage unverified. Hood is unlined and the fiberglass is wearing out rubbing against door.																						
		_							-		-		•	-								
<u> </u>																						
6/22/2023																						
	EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE												_									
		By sig	gnature ab	ove I do	hereby	certify al	I info	rmation co	ontained v	<u>with</u> in	this report to b	<u>oe t</u> r	ue and accur	ate to the be	st of my know	ledge at p	rese	nt.				