RTR Services Inc.			c.								RTR #: 3063461									
HEAVY TRUCK											ACCOUNT NUMBER:									
CONDITION REP			RT								ACCOUNT NAME:									
YEAR:		2019		MI	MILES 563			360			VIN#: 1FUJHHDR9KLKT0957			957						
MAKE:		Freigthliner	G۱	GVW : 53,30		00	LICENSE:					ST:		TAGS:	MON	TH		YR:		
MODEL:		Cascadia 126		WI	WHEELBASE:			235		COLOR: E		E					INTERIOR:		Gray	
ENGINE:		DD15 L6 14.8L		HF	HP 455		В	ODY TYP			leeper		KEYS: IGNITION: ⊠ YES		□ NO	•	DOOR:	OOR: X YES NO		
TRANS:		Automatic			IEL: [GAS	\boxtimes			ANT			ESTED: YES N		NO	RATI	ATING:		•	
DOES M		OTOR RUN?		S) (AN IT BE DRI					□ NO COLLISION D		ISION DA	MAGE?		☐ YES ⊠ NO		10
								Pi	HYSICA	AL A	PPEARAI	NC	E							
	FDONT	DUMPED	GD	FR	PR	N/A	_	СОММ	ENTS									OPT WR STE	IONS	
	FRONT BUMPER HEAD LIGHTS HOOD						-									⊠ BF	P RAK	_	ERING	
				\boxtimes]											∃ AIR		
	TURN SIGNALS]] HYD		
	GRILL D FRONT FENDER				+ $=$											$-\mid \boxtimes \boxtimes$		WR LOC	-	
BODY	D DOO			\parallel											$\dashv \stackrel{\bowtie}{\boxtimes}$		WR SEA			
	D SLEEPER			\boxtimes]										Ρ	WR MIR		
	REAR BUMPER		_													$\perp \mid \boxtimes$		IR CONI	_	
	TAIL LIGHTS														$-\mid \boxtimes \boxtimes$		IR RIDE			
	P FRONT FENDER			\boxtimes]										С	ONV. 5 ^T	H WHEE	EL
	P FRONT DOOR]									$\square \bowtie$		LIDING		EEL
	P SLEEPER						_									$\dashv \exists$		M FM R. APE / CI		,
	D FRONT			\boxtimes							22 SIZE:							LEEPER		
	D REAR A1 (S/D?)]	90 % 2										LECTRI		GTAIL
TIRES				\boxtimes				90 % 2			SIZE: 22 SIZE:					_ ⊠ FI		LAD HA TANKS	NDS	
Ĕ	P REAR A1 (S/D?)				\parallel			90 % 2								٦.,		SINGL	E GAL	
	P REAR A2 (S/D?)			\boxtimes]	75 % 2									\triangleright	☑ DUAL	GAL _	
SS	SPARE [$+$ \vdash			%	S	IZE:					_	M HEE	IUD FLA	PS	
	D FRONT DOOR															- **		.LS] ALUM	INUM	
LAS	REAR WINDOW			\boxtimes]											STEEL	-	
G	P FROM	NT DOOR														_] BUD] SPOKI	=		
DASH		N.S			+	╁┢										\neg	_	XHAUS		
OR	DOOR PANELS			\boxtimes]									SL	ISPI	ENSION		
	SEAT(S	EAT(S)]											AIR	_	
INTER] SPRIN] PAD	G	
_	SLEEPER				1 🗇											\neg	_	ANDEM	AXLE	
	ENG!!	GD	FR	PR	UK		N/A	COMN									NGINE E			
낚	ENGIN									gine Ligh Supply L		,			┦믬		OOL BO			
MECHANICAL	TRANSMISSION CLUTCH								ITAIIS	All !	опрыу Е	<u> </u>	<u> </u>			ᅴᆸ		VET KIT	AALL	
₹	DIFFERENTIALS			\boxtimes]										M	lini Frido	ge	
딥	_								Brake	Air	Supply P	res	ssure Lov	V		$\exists \exists$				
Σ	FRONT END			\parallel		-									ᆸ					
BATTE		RY/ELECTR		\boxtimes]													
COMMENTS: Mileage unverified. ABS Not working, service required. Top D/S Fairing missing, bottom P/S Fairing missing.																				
								7/2	5/202	3										
		EMPLOYEE'S FULI By sig					ıll info	ormation co	DATE ntained wi		nis report to b	e tr	ue and accur		MPLOYEE'S st of my know			nt.		_