RTR Services Inc.						_	7			RTR #: 306483						3				
HEAVY TRUCK							ACCOUNT NUMBER:													
CONDITION REPORT											ACCOUNT NAME:									
YEAR:		2016		MIL	LES	600,98	2	VI	VIN#: 3AKJGLDV7G			/7GSGl	J6040							
MAKE:		Freightliner		GV	<b>GVW</b> : 52,500		LICEN	LICENSE:				ST: T		TAGS	: N	IONTH	ł	YR:		
MODEL:		Cascadia		WH	WHEELBASE:		236"		COLOR: EX		EX.	XTERIOR: Burgar		gandy	ndy IN		INTERIOR:			
ENGINE:		Detroit		HP	HP		BODY TYPE: S		Sleeper	Bleeper			KEYS: IGNITION: YES			NO • DOOR:  YES  N				
TRANS:		Automatic	FU	EL: 🗆	GAS	GAS 🖾 DIESEL				TESTED: 🗵		YES [	YES 🗆 NO		RATING	3:	-10F			
DOES M		OTOR RUN?	RRUN?   XES		□ NO		AN IT BE DRIVE					□ NO COLLISION		LISION D	AMA	GE?	☐ YES ☐ NC		NO	
							Р	HYSICA	L APPE	EARA	NCI									
ВОДУ		GD	FR	PR	N/A	COMM	IENTS										PTIONS			
	_	BUMPER		$\boxtimes$												⊠ BRA		TEERING	ì	
	HEAD LIGHTS HOOD TURN SIGNALS GRILL															NES ⊠ AIR				
				$\boxtimes$																
				$\boxtimes$											☐ PWR LOCKS					
	D FROM					Dama	Damage by headlight/scrapes								_	PWR WINDOWS PWR SEATS				
	D DOOR															☐ ☑ PWR SEATS ☐ ☐ PWR MIRRORS				
	REAR BUMPER				H											_		NDITION	IER	
	TAIL LIGHTS		$\boxtimes$														DE SEAT			
	REAR PANEL   P FRONT FENDER																DE SUSP 5 <sup>TH</sup> WHE			
	P FRONT DOOR			$\boxtimes$														5 <sup>···</sup> WHE G 5 <sup>TH</sup> WH		
																		RADIO		
	TOP																CD / CB			
TIRES	D FRONT			Ш			% 35	SIZE: 29	95/75R2	22.5							SLEEP 5'x77"x	ER SIZE	?	
	D REAR A1 (S/D?)						% 35	SIZE: 27	75/80R2	22.5								RICAL P	IGTAIL	
	D REAR A2 (S/D?)				$\boxtimes$			SIZE: 27								_		HANDS		
	P FRONT			$\boxtimes$			SIZE: 29 SIZE: 27								_					
	P REAR A2 (S/D?)							SIZE: 27 SIZE: 27									_	GLE GAL AL GAL 8		
	SPARE					$\boxtimes$	%	SIZE									MUD FI			
GLASS	WINDSHIELD			]												WHE	_			
	D FRONT DOOR REAR WINDOW																⊠ ALU ☐ STE	MINUM		
	P FRONT DOOR																			
	MIRRORS				$\boxtimes$		Driver	side da	mage											
~	DASH																	ST S/D?		
INTERIOF	DOOR PANELS SEAT(S)																PENSIC ⊠ AIR	N		
																		ING		
	HEADLINER			$\boxtimes$																
	SLEEPER   CD		GD	⊠ FR	PR	UKN	N/A	COMM	IENTS:							=		M AXLE E BRAKE	=	
MECHANICAL	ENGINE TRANSMISSION			FK			N/A	COMIN	IEN I 5:							_	TOOL E		-	
				$\boxtimes$														AG AXLE		
	CLUTCH															_	WET K	IT		
	DIFFERENTIALS BRAKES																			
	BRAKES FRONT END				\															
	REAR END			$\boxtimes$																
		RY/ELECTR		The					atteries					aak Fass	ma !!			2000 45		
COMMENTS: Mileage unverified. The start block message that showed at recovery, did go away. Check Engine light is on. Damage to passenger side lower fairing. Damage to rear metal rack/platform. Damage to driver side mirror. oil build up near the oil filler neck.																				
	-						-													
07-18-2023																				
		EMPLOYEE'S FULI	L NAME (I	PLEASE	PRINT	)		DATE		_	-			EMPLOYEE	'S SIG	NATUR	<u> </u>			
							nformation co			port to b	e tru	e and accu	rate to the	best of my kn						