RTR Services Inc. BOX TRUCK CONDITION REPORT										RTR #: 3083325-01 ACCOUNT NUMBER: ACCOUNT NAME:					
<b>YEAR:</b> 2020				MIL	ES	143,532				VIN#: 1HA3GTCG4LN000847					
MAKE: Ch		Chevrolet		GV	W:	15,000	15,000 <b>BOX</b>			BOX LEN	IGTH	BOX	NIDTH		
MODEL: Ex		Express	ess		WHEELBAS		SE:		COLOR: EXTERIOR: White		INTERIOR: Gray				
ENGINE: 6.8		6.8L V8	L V8		HP				KEYS: IGNITION: ⊠ YES □ NO • DOOR:						
TRANS: Automatic		-					. AN	NTIFREEZE TESTED: 🗌 YES 🖾 NO		YES 🖾 NO	RATI	IG:			
DOES MOTOR RUN? YES DO CAN IT BE DRIVEN? YES NO COLLISION DAMAGE? YES NO PHYSICAL APPEARANCE														S 🛛 NO	
			<b>6</b> D	==		N1/A				ANCE				PTIONO	
BODY	FRONT BUMPER		GD	FR PR		N/A	COMN	IENIS					DPTIONS TEERING		
	HEAD L	HEAD LIGHTS HOOD TURN SIGNALS		$\boxtimes$								_	BRAKES		
				$\boxtimes$									_ □ AIR ⊠ HYD		
	GRILL			$\boxtimes$											
	D FRONT FENDER			$\boxtimes$										INDOWS	
	D DOOR D BOX			$\boxtimes$			Dama	no to ton	front of Bo	v				EATS IRRORS	
		REAR BUMPER					Dama	ge to top		×		ᅴ님		NDITIONER	
	TAIL LIGHTS			$\boxtimes$										DE SEAT D/P	
		REAR PANEL P FRONT FENDER		$\boxtimes$									AIR RIE AM FM		
		P FRONT DOOR		$\boxtimes$										CD / CB?	
	P BOX			$\boxtimes$											
TIRES	TOP D FRONT			$\boxtimes$			80	% LT225	75R16 SI	Έ:				LUCENT ROOF	
	D REAR A1 (S/D?)			$\boxtimes$					75R16 SI			$\square$	BOX D	OME LIGHT	
	D REAR A2 (S/D?)							%	SIZE:	-			SIDE D		
	P FRONT P REAR A1 (S/D?)			$\boxtimes$			80 80/80		75R16 SI 75R16 SI				EL TANK	S GLE GAL	
	P REAR A2 (S/D?)					$\boxtimes$		% SIZE:							
	SPARE WINDSHIELD							%	SIZE:				MUD FI EELS	LAPS	
LASS	D FRONT DOOR			$\boxtimes$										MINUM	
		REAR WINDOW				$\square$							STE STE		
G		P FRONT DOOR MIRRORS		$\boxtimes$											
	DASH			$\boxtimes$									_	IST S/D? <u>S</u>	
Ř		DOOR PANELS SEAT(S) FLOORING		$\boxtimes$								SU	SPENSIO	DN	
RIOR												_	□ AIR ⊠ SPR	ING	
INTE	HEADLI	HEADLINER		$\boxtimes$									🗌 PAD	)	
=	SLEEPER														
	BOX		GD	FR	PR		N/A	N/A COMME					TOOL E	E BRAKE BOX	
MECHANICAL		ENGINE TRANSMISSION		$\boxtimes$									LIFT/TA	AG AXLE	
													RAMP LIFT G/	ATE	
		DIFFERENTIALS		$\square$								ㅓ님	LIFT G		
	BRAKES			$\boxtimes$											
	FRONT END REAR END			$\boxtimes$											
	BATTERY/ELECTR			$\boxtimes$											
							$\boxtimes$	n de cr. M	alt h.a					4	
COMMENTS: Mileage unverified. Back door not able to get in door. Unit has a special lock and has a safety switch under the steering wheel that needs to be pressed before it is able to go in drive or any other gear.															
							00	/17/202	<b>`</b>						

08/17/2023

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107