RTR Services Inc.												RTR #: 3083654								4				
BOX TRUCK											ACCOUNT NUMBER:													
CONDITION REPORT										ACCOUNT NAME:														
YEAR: 2016		2016		MII	LES	351,4	87				VIN#: 1FVACWDT2GHGY5611													
MAKE: Frei		Freightliner		G۷	W:	25,50	00	ВО	X HEIGI		BOX LENGTH				В	BOX WIDTH								
MODEL:		M2 106	106			BASE:					COLOR: EXTERIOR: White				INTERIOR: Gray									
ENGINE:		Cummins	HP					1	KEY	EYS: IGNITION: 🛛 YES 🗌 NO 🔹 DOOR:					ર: ⊠	⊠ YES □ NO								
TRANS:		Automatic	1		EL:	GAS		DIESEI	L A	ANT	NTIFREEZE TESTED: ☐ YES ☒ NO						R	ATIN	G:					
DOES MOTOR RUN?			⊠ YE	s I	□ NO)	CAN	N IT BE DRIVE			⊠ YES		□ NO		COLLI	SION D	AMA	GE?	☐ YE	S	⊠ NO			
										AL A	APPEAR	ANC	Ε											
ВОДУ	FRONT BUMPER		GD	FR 🖂	PR □	N/A		COMN	MENTS							\square	OPTIONS PWR STEERING							
	HEAD LIGHTS HOOD TURN SIGNALS GRILL			\boxtimes												BRA			KING					
				\boxtimes														□ □ AIR						
				\boxtimes				Paint Peeling											☐ HYD PWR LOCKS					
	D FRONT FENDER			\boxtimes	ΤĦ			- and rooming										☐ PWR WINDOWS						
	D DOOR			\boxtimes											=	_								
	D BOX REAR BUMPER																		☐ PWR MIRRORS☒ AIR CONDITIONER					
	TAIL LIGHTS			\boxtimes														☐ AIR RIDE SEAT D/P ☐ AIR RIDE SUSPENSIO☐ ☐ AIR RIDE SUSPENSIO☐ ☐ AM FM RADIO☐ ☐ TAPE / CD / CB? CD						
		P FRONT FENDER																				ION		
	_	P FRONT DOOR		\boxtimes			_	Crack	ed															
	P BOX			\boxtimes															SLEEP	ER S	SIZE?			
	TOP D FRONT			\boxtimes				50 %		SIZE								=			ENT RO	DF		
TIRES	D REAR A1 (S/D?)			\boxtimes				50 %		SIZE								☐ E-TRACK LINING ☐ BOX DOME LIGHT						
	D REAR A2 (S/D?)					\boxtimes		%		SIZE:								SIDE DOOR						
		P FRONT P REAR A1 (S/D?)		\boxtimes				50 % SIZE: 50 % SIZE:						FUEL TANKS ⊠ SINGLE GAL										
	P REAR A2 (S/D?)						l	% SIZE: % SIZE:						DUAL GAL										
	SPARE														MUD FI	S								
GLASS	WINDSHIELD D FRONT DOOR			XI XI				Crack							_ WHEELS □ ALUMINUM									
		REAR WINDOW P FRONT DOOR MIRRORS		\boxtimes															⊠ STE		•			
ច															_ □ BUD □ SPOKE									
	DASH				+ $=$	╁												П	EXHAU		S/D?			
œ	DOOR PANELS			\boxtimes														SUSPENSION						
RIO		SEAT(S) FLOORING						Both seats torn			& ripped						☐ AIR ☐ SPR	ING						
INTERI		HEADLINER																						
=		SLEEPER																_	TANDE					
	вох		GD	FR	PR	UK		N/A COMM			ENTS:						_	ENGINI TOOL E						
MECHANICAL	ENGIN			\boxtimes						MIL lamp on							☐ LIFT/TAG AXLE							
		TRANSMISSION CLUTCH DIFFERENTIALS																	RAMP LIFT G	^ TE				
								\square											LIFT G	AIE				
		BRAKES		\boxtimes																				
		FRONT END REAR END		\boxtimes																				
	BATTERY/ELECTR							ä	New batteries 01/2024															
		REFRIGERATION						\boxtimes									ia!::í		.4ue	a w 1 -	انت الممم			
COMMENTS: Mileage unverified. Rec'd email from Bonnie at yard- Keys have been cut, batteries replaced, U joint and straps replaced, and driveshaft reattached. Unit starts, runs and moves. The Malfunction Indicator Lamp (MIL) is illuminated. It does have a flat tire. Bonnie will send												end												
me a photo and an estimate for repair, if needed. It's possible it just may need air.																								
		EMPLOYEE'S FUL	L NAME (P	LEASE	E PRINT)			DAT	E		_			E	MPLOYEE	'S SIG	NATUR	lE					
							ll infor	mation c			is report to b	e true	and acc	curate										