RTR Services Inc. HEAVY TRUCK											RTR #: 308383 ACCOUNT NUMBER:						1			
CONDITION REPORT YEAR: 2016				MILES 488,053						ACCOUNT NAME: VIN#: 3HSDJSNR4GN128672										
MAKE:		International	<u> </u>		w:	52,000		ENSE:						TAGS:	мо	NONTH		YR:		
MODEL:		Prostar+122		WH	IEELE	BASE: 445		-	COLOF		EXTER	EXTERIOR: Gray			INTE		OR:	Fray	<u> </u>	
ENGINE:		Navistar N13 13L		HP		E	PE:													
т	RANS:	10 Speed Ma	FU	EL:] GAS 🛛		L	ANTIFREEZE T		TESTE	ESTED: 🗌 YES 🖾 NO			RA	TIN	G:				
DOES MOTOR RUN? X YES			s [C	AN IT BI		EN?		6 🗆 1	NO	COLL	ISION DA	MAG	E?	🗆 YES		0		
							P	HYSIC	AL AF	PPEARA	NCE									
	FRONT BUMPER		GD	FR	PR	N/A	COMM	IENTS								ব	OPT PWR STE			
BODY	-	LIGHTS		\boxtimes												_	KES		•	
	HOOD			\boxtimes																
	TURN SIGNALS GRILL			\boxtimes											— D			CKS		
	D FRONT FENDER			\boxtimes												_	PWR WIN		;	
	D DOOR D SLEEPER			\square												_	PWR SEA			
	REAR BUMPER															_	AIR CON		ER	
	TAIL LIGHTS			\boxtimes													AIR RIDE			
	REAR PANEL P FRONT FENDER														┥╘		AIR RIDE CONV. 5 ^T			
	P FRONT DOOR			\boxtimes													SLIDING			
	P SLEEPER TOP			\square												_	AM FM R	-		
TIRES	D FRONT						80 %	11R22.	5 SIZ	:E:							TAPE / C SLEEPEF			
	D REAR A1 (S/D?)			\boxtimes				445/50								ELECTRICAL PIGTAIL				
	D REAR A2 (S/D?)			\boxtimes				80 % 445/50R22.5 SIZE: 80 % 11R22.5 SIZE:							_	GLAD HANDS				
	P REAR A1 (S/D?)			\boxtimes						.5 SIZE:					- ·	SINGLE GAL <u>80</u>				
	P REAR A2 (S/D?)			\boxtimes			80 %	445/50												
SS	SPARE WINDSHIELD							%	S	IZE:							MUD FLA	PS		
	D FRONT DOOR			\boxtimes																
3LAS	REAR WINDOW P FRONT DOOR			\boxtimes														-		
0	MIRRORS			\boxtimes														E		
TERIOR	DASH			\boxtimes												_	EXHAUS		<u>s_</u>	
	DOOR PANELS SEAT(S)			\boxtimes											s	SUS	PENSION			
	CARPET					\boxtimes												IG		
INT				\square																
	SLEEPER		GD	FR	PR		N/A	COM	MENT	S:						_	TANDEM ENGINE			
MECHANICAL	ENGINE TRANSMISSION CLUTCH DIFFERENTIALS							Chec	k Eng	ine Ligh	nt					Ξ	TOOL BC			
				\boxtimes											$\exists E$	=	LIFT/TAG WET KIT			
				\boxtimes													Hydraulic	; fluid t	ank	
	BRAKES			\boxtimes												\triangleleft	Super Sir			
	FRONT END REAR END			\boxtimes											-					
	BATTE	RY/ELECTR		\boxtimes																
This is Not a Mechanical Inspection Report / It is a Visual Inspection Only - DEF & DPF Functions Not Verified, Buyer Responsible to Validate. COMMENTS: Mileage unverified.													lidate.							
COMMENTS. MILEAYE UTVETTIEU.																				
								00.00												

08-02-2023

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107