RTR Services Inc. BOX TRUCK CONDITION REPORT		RTR #:	3103206
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2013	MILES	Unknown		VIN#:	3FRNF7FAXDV034489			
MAKE:	Ford	GVW:	2600	BOX HEIGHT	8ft	BOX LENGTH	25ft	BOX WIDTH	8ft
MODEL:	F750 Super Duty	WHEELBASE:	23ft	COLOR: EXTERIOR:	White	INTERIOR:	Gray		
ENGINE:	Cummins ISB Diesel	HP		KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	Automatic	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☒ YES ☐ NO		RATING:			
DOES MOTOR RUN?	☒ YES	☐ NO	CAN IT BE DRIVEN?	☒ YES	☐ NO	COLLISION DAMAGE?	☐ YES	☒ NO	

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☒	☐	☐	Damage
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	Damage
	TURN SIGNALS	☐	☒	☐	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	
	D DOOR	☐	☒	☐	☐	
	D BOX	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P BOX	☐	☒	☐	☐	Scratches
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	40 % 295/75R 22.5 SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	40 % 295/75R 22.5 SIZE:
	D REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	P FRONT	☐	☒	☐	☐	40 % 295/75R 22.5 SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	40 % 295/75R 22.5 SIZE:
	P REAR A2 (S/D?)	☐	☐	☐	☒	% SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	FLOORING	☐	☒	☐	☐	
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☐	☐	☒	
	BOX	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☒	☐	☐	☐	
	TRANSMISSION	☐	☒	☐	☐	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIALS	☐	☒	☐	☐	☐	
	BRAKES	☐	☒	☐	☐	☐	
	FRONT END	☐	☒	☐	☐	☐	
	REAR END	☐	☒	☐	☐	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	
	REFRIGERATION	☐	☐	☐	☐	☒	

OPTIONS

- ☒ PWR STEERING
- BRAKES
  - ☐ AIR
  - ☐ HYD
- ☐ PWR LOCKS
- ☐ PWR WINDOWS
- ☐ PWR SEATS
- ☐ PWR MIRRORS
- ☒ AIR CONDITIONER
- ☐ AIR RIDE SEAT D/P _____
- ☐ AIR RIDE SUSPENSION
- ☒ AM FM RADIO
- ☐ TAPE / CD / CB? _____
- ☐ SLEEPER SIZE? _____
- ☐ TRANSLUCENT ROOF
- ☒ E-TRACK LINING
- ☐ BOX DOME LIGHT
- ☐ SIDE DOOR
- FUEL TANKS
  - ☒ SINGLE GAL _____
  - ☐ DUAL GAL _____
- ☒ MUD FLAPS
- WHEELS
  - ☐ ALUMINUM
  - ☒ STEEL
  - ☐ BUD
  - ☐ SPOKE
- ☐ EXHAUST S/D? _____
- SUSPENSION
  - ☐ AIR
  - ☒ SPRING
  - ☐ PAD
- ☐ TANDEM AXLE
- ☐ ENGINE BRAKE
- ☐ TOOL BOX _____
- ☐ LIFT/TAG AXLE
- ☐ RAMP
- ☒ LIFT GATE
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

COMMENTS: Mileage unverified. Nothing on the dash comes on or lights up, including the odometer reading. Paint chips, scratches, dents/dings throughout.

11/1/2023

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107