RTR Services Inc. GENERAL EQUIPMENT			RTR #: ACCOUNT	3103588-Trailer	
CONDITION REPORT			ACCOUNT NAME:		
YEAR:	2023				
MAKE:	Concrete Eq. Co.	🗌 YES 🖾 NO	EQUIPMENT WAS IN USE AT THE TIME OF R	RECOVERY	
MODEL:					
SN:		NON OPERATIONAL			
POWER:					
DESCRIPTION:	Lil Bubba Equipment Caddy with Toolbox, & Titan Curb Mixer				
SHOT / COUNT / HOUR:					
NOTES / COMMENTS: VIN: 1T9TC0612PF716873					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #: ACCOUNT ACCOUNT NAME:	3103588-Curb Machine		
YEAR:	2023					
MAKE:	Li Bubba	🗌 YES 🖾 NO	EQUIPMENT WAS IN USE AT THE TIME OF F	RECOVERY		
MODEL:	Hornet EP	Ø OPERATIONAL				
SN:		NON OPERATIONAL				
POWER:	Gas					
DESCRIPTION:	Curb Machine					
SHOT / COUNT / HOUR: N/A						
NOTES / COMMENTS: Doesn't appear to have been previously used. Has tools and stamps.						

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: ACCOUNT ACCOUNT NAME:			
YEAR:					
MAKE:		🗌 YES 🗌 NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:					
SN:					
POWER:					
DESCRIPTION:					
SHOT / COUNT / I	SHOT / COUNT / HOUR:				
NOTES / COMME	NTS:				

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107