RTR Services Inc. HEAVY TRUCK CONDITION REPORT											RTR #: 3111935 ACCOUNT NUMBER: ACCOUNT NAME:								3			
		2016				710,130	,		VIN#: 3HSDJSNR3GN206942													
MAKE:		International		GV	w:	,			_			6	ST:		TAGS:	MON	ΙТΗ		YR:			
MODEL:		Prostar		WH	WHEELBASE:				COLOR:		R: E				INTE	RIC	DR:					
ENGINE:		N13	НР	,	B	BODY TYPE:																
т	RANS:	Automatic		FU	EL: [] GAS 🖂									RATING:							
		OTOR RUN?	🛛 YE				AN IT BE								ISION DA						_	
								HYSIC/		_							-					
					PR	N/A	COMM	IENTS										OPT	IONS			
BODY	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS GRILL D FRONT FENDER D DOOR							<u> </u>									PWR STE	ERIN	G			
				\boxtimes					<u> </u>					Br		KES] AIR						
				\boxtimes																		
																		PWR LOO		_		
				\boxtimes			Small	Small hole above tire									☑ PWR WINDOWS☑ PWR SEATS					
	D SLEEPER																	PWR MIR		;		
		REAR BUMPER		IN														AIR CON				
		TAIL LIGHTS REAR PANEL		\boxtimes												$\square \boxtimes$		AIR RIDE AIR RIDE	-		N	
	P FRONT FENDER			\boxtimes													(CONV. 5 ^T	H WHE	EL		
	P FRONT DOOR			\boxtimes														SLIDING		IEEL		
	P SLEEPER TOP			\boxtimes												\square		AM FM R. Tape / Ci		?		
TIRES	D FRONT			\boxtimes			70 %		SIZE									SLEEPEF			_	
	D REAR A1 (S/D?)			\boxtimes			90 %		SIZE							\square				IGTAIL	L	
		D REAR A2 (S/D?) P FRONT		\boxtimes			90 % 90 %		SIZE Size									GLAD HA . TANKS	NDS			
	P REAR A1 (S/D?)			\boxtimes			70 %	;	SIZE	:							[_	
	P REAR A2 (S/D?) SPARE						90 %		SIZE										-			
	WINDSHIELD							%		SIZE:								MUD FLA ELS	122			
SS	D FRONT DOOR			\boxtimes													-					
G REAR D P FRO MIRRO			\boxtimes										STEEL									
				\boxtimes													-	_ 600 □ SPOK	Е			
	DASH DOOR PANELS			\boxtimes														EXHAUS			_	
ERIOR					\square											SU		PENSION				
ĒR		SEAT(S) CARPET																_ AIR _ Sprin	IG			
INT	HEADLINER			\boxtimes													[_ PAD				
	SLEEPER		GD	⊠ FR	PR		N/A	COMM		те	_					\exists		TANDEM ENGINE I				
MECHANICAL	ENGINE							COMIN		13.						님		FOOL BC		-		
	TRANS	TRANSMISSION				\boxtimes											I	LIFT/TAG				
	CLUTCH DIFFERENTIALS					\boxtimes										ᅴ님		WET KIT				
	BRAKES															ᅴᆸ						
	FRONT END			\boxtimes																		
	REAR END BATTERY/ELECTR		\square	\square				New 1	2/20	/2023												
COMMENTS: Mileage unverified. Unit starts and runs but has a loud noise, potentially related to the air compressor or air system. Doesn't build												lild										
air and is not able to be driven. The Malfunction Indicator Light (MIL) is illuminated on the dash.																						
		12/08/2023																				

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107