| RTR Services Inc. TRAILER CONDITION REPORT | | RTR #: | 3113301 |
|---|---|---|---|
| | | ACCOUNT NUMBER: | |
| | | ACCOUNT NAME: | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| YEAR: | 2015 | BODY TYPE: | Reefer | VIN#: | 1GRAA062XFB702078 | | | | |
| MAKE: | Great Dane | LICENSE: | | STATE: | | TAGS: MN: | | YR: | |
| MODEL: | | COLOR: EXTERIOR: | White | | | INTERIOR: | White/Steel | | |
| LENGTH: | 53' | WIDTH: | 102: | HEIGHT: | 13'6" | GVW: | 68,000 | | |

HITCH: ☐ GOOSE NECK ☐ PINTLE ☒ 5TH WHEEL PIN ☐ 1 7/8" BALL ☐ 2" BALL ☐ 2 5/16" BALL

| IS IT ROAD READY? | ☒ YES | ☐ NO | COLLISION DAMAGE? | ☐ YES | ☒ NO | KEYS: | ☐ YES | ☒ NO |
|---|---|---|---|---|---|---|---|---|

## PHYSICAL APPEARANCE

| | | GD | FR | PR | N/A | COMMENTS |
|---|---|---|---|---|---|---|
| BODY | FRONT PANEL | ☐ | ☒ | ☐ | ☐ | |
| | HITCH | ☐ | ☒ | ☐ | ☐ | |
| | D SIDE PANEL | ☐ | ☒ | ☐ | ☐ | Back end driver side has dent/damage |
| | SIDE DOOR (S) | ☐ | ☐ | ☐ | ☒ | |
| | REAR PANEL | ☐ | ☒ | ☐ | ☐ | |
| | REAR DOOR (S) | ☐ | ☒ | ☐ | ☐ | |
| | P SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | REAR BUMPER | ☐ | ☒ | ☐ | ☐ | |
| | TOP | ☐ | ☒ | ☐ | ☐ | |
| INTERIOR | FLOOR | ☐ | ☒ | ☐ | ☐ | |
| | D SIDE PANELS | ☐ | ☒ | ☐ | ☐ | |
| | FRONT PANEL | ☐ | ☒ | ☐ | ☐ | |
| | P SIDE PANEL | ☐ | ☒ | ☐ | ☐ | |
| | CARGO RAILS | ☐ | ☐ | ☐ | ☒ | |
| | CEILING | ☐ | ☒ | ☐ | ☐ | |
| TIRES | D FRONT | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | D REAR A1 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 50 SIZE: 295/75R/22.5 |
| | D REAR A2 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 50 SIZE: 295/75R/22.5 |
| | D REAR A3 (S/D?) | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | P FRONT | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | P REAR A1 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 50 SIZE: 295/75R/22.5 |
| | P REAR A2 (S/D?) | ☐ | ☒ | ☐ | ☐ | % 50 SIZE: 295/75R/22.5 |
| | P REAR A3 (S/D?) | ☐ | ☐ | ☐ | ☒ | % SIZE: |
| | SPARE | ☐ | ☐ | ☐ | ☒ | % SIZE: |

| | | GD | FR | PR | UKN | N/A | COMMENTS: |
|---|---|---|---|---|---|---|---|
| MECHANICAL | TAIL LIGHTS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | SIGNAL LIGHTS | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | CLEARANCE LGT | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | SLIDER AXLES | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | REFRIGERATION | ☐ | ☒ | ☐ | ☐ | ☐ | Hours say failure |
| | LANDING GEAR | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | AIR HOSE/GLAD | ☐ | ☒ | ☐ | ☐ | ☐ | |
| | ELECTR PIGTAIL | ☐ | ☒ | ☐ | ☐ | ☐ | |

| OPTIONS | |
|---|---|
| ☒ | AIR RIDE SUSPENSION |
| ☐ | SPRING SUSPENSION |
| ☒ | AIR BRAKES |
| ☐ | ELECTRICAL BRAKES |
| ☐ | HYD BRAKES |
| ☒ | SLIDER AXLE |
| | WHEELS |
| ☐ | BUD |
| ☐ | SPOKE |
| ☒ | STEEL |
| ☐ | ALUMINUM |
| ☐ | LIFT/TAG AXLE |
| ☐ | SPARE TIRE RACK |
| ☒ | REFIGERATION UNIT |
| ☒ | REEFER HRS Unknown |
| ☐ | TOOL BOX |
| ☒ | MUD FLAPS |
| ☐ | ROLL UP REAR DOOR |
| ☐ | LOADING RAMP |
| ☒ | BATTERY |
| ☒ | SIDE SKIRT |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |
| ☐ | |

COMMENTS: Hours unknown/unverified. Unit is reported to run and get cold. Hour meter reads "failure"

| 11/29/2023 | |
|---|---|
| EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE |

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.



The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107