RTR Services Inc.											RTR #: 4013909-01										
TRAILER CONDITION REPORT					00						ACCOUNT NUMBER: ACCOUNT NAME:										
YEAR: 2014					BODY	TYPE:	Reefer			VIN#: 1GRAA06				7 02	2065						
MAKE: Great Dane					LIC	ENSE:				STATE:				TAGS: MN:				YR:			
MODEL: X2100 Carrier					COLOR:		EXTERIOR: W			hite			INTERIOR:			RIOR:	White/Steel				
LENGTH: 53'			WIDTH:			102"			HEIGHT: 13'6"						GVW : 68,000			0			
HITCH: GOOSE N		ECK	☐ PI	NTLE	⊠ 5 TH	WHEE	L PIN	17	7/8" BALL 🔲 2" BALL			BALL	☐ 2 5/16" BA			ALL					
IS IT ROAD READY? ⊠ YES					□ NO		COLLISION DAMA			GE? YES N			⊠ No	O KEYS			S: TES			⊠ NO	
PHYSICAL APPEARANCE																					
			GD	FR	PR	N/A	COMI	MENTS						OPTIONS							
ВОДУ	FRONT PANEL HITCH D SIDE PANEL			\boxtimes															_	USPENSIO ISPENSION	
																		AIR BR			•
	SIDE DOOR (S)																	_	_	AL BRAKES	S
	REAR PANEL REAR DOOR (S)			\boxtimes	\parallel													HYD BI SLIDER		_	
	P SIDE PANEL			\boxtimes													_	IEELS			
	REAR BUMPER TOP																				
	FLOOR		ö	\boxtimes														STE	EL		
INTERIOR	D SIDE PANELS FRONT PANEL			\boxtimes														⊠ ALU LIFT/T/			
	P SIDE PANEL																H			E RACK	
	CARGO RAILS																			TION UNIT	
TIRES	D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?) D REAR A3 (S/D?) P FRONT P REAR A1 (S/D?) P REAR A2 (S/D?) P REAR A3 (S/D?) SPARE				H		%	SIZE:										TOOL		RS <u>17,103</u>	
					□ □ □ % 25 SIZE: 295/75R/22.5 □								\boxtimes								
							% 50 SIZE: 295/75R/22.5 % SIZE:								LOADII		EAR DOOF	₹			
							%	SIZE:									\boxtimes	BATTE			
-						SIZE: 295															
							%	SIZE:	,	W											
			GD	FR	☐ PR	UKN	% N/A	SIZE: COMMI	TINT	'C.											
CHANICAL	TAIL LIGHTS SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION LANDING GEAR AIR HOSE/GLAD ELECTR PIGTAIL							COMM	2111	Б.							Ħ				
				\boxtimes																	
				\boxtimes																	
ME				\boxtimes																	
COMMENTS: Hours unverified. Passenger front outside tire flat and off rim. Passenger front inside tire bad capping on inside. White paint on outside of trailer. Cover on roof corner falling down. Scuffs and scratches throughout interior and exterior.																					
Takendo S. Manor. Cover on 1001 Corner raining downs obtain and solutiones throughout interior and exterior.																					
<u> </u>																					
	_						_01	/30/2024	1												
		EMPLOYEE'S FULL By sig	,			ertify all inf	ormation c	DATE ontained withi	n this	report to	be true a	and acc	curate to t			YEE'S SIG y knowledg			_		