	DTD Com	vione Inc											RTR #:	40420	77			
RTR Services Inc. PICK-UP TRUCK					5			ACCOUN					RTR #: 4013977 NUMBER:					
CONDITION REPORT			C			ACCOUNT NAME:												
YEAR: 2017			V	VIN:			2REC	OHF1620	2020			MILES:	122	122,817				
MAKE: GMC				L	ICENS	E:				STATE					MN:	MN:		
	MODEL:	Sierrra 250	0HD	С	AB TY	Crew	Cab	COI	LOR:	EX	(TERIOR:	Gray		INTER	IOR:	Gray		
ENGINE: 6.0L V-8			K	EYS:	IGNITIO	N: ⊠ YES □ NO · DOOR: ⊠ YES □ NO												
TRANS: Automatic			F	UEL:	⊠ GAS	B ☐ DIESEL ☐ HYBRID ANTIFREEZE TESTED: ☐ YES								S 🖾 NO	RATII	NG		
DOES MOTOR RUN? 🛚 YES				S	□ NO	С	AN IT BE DRIVEN? YES NO COLLISION DAI						/IAGE?	☐ YE	S ⊠	NO		
					PHYSICAL APPEARANCE													
	FRONT BUMPER		GD 🗆	FR 🖂	PR □	N/A	COMMENTS Dented										TIONS EERING	
	HEAD LIGHTS			\boxtimes			Dei	iteu								PWR B		•
	HOOD TURN SIGNALS GRILL															PWR LC	-	•
					\mathbb{R}											PWR W	_	3
ВОДУ	D FRONT FENDER			\boxtimes											\square	LEATHE		
	D DOOR D REAR FENDER				\mathbb{R}											PWR MI		
	CARGO BED			\boxtimes												TILT W	IEEL	
	REAR BUMPER TAIL LIGHTS															TINTED AIR CO		
	TAIL GATE			\boxtimes			Den	ted								CUSTO		
	TAIL PIPE				무											SUN RC	-	
	P FRONT FENDER P DOOR			\boxtimes	\parallel											AM FM TAPE D		
	P REAR FENDER			\boxtimes												CD PLA		
TOP D FRON					H믐		70	% 265	70R/18	SIZE:						CUSTO	W WHE	ELS
RES	D REAR			\square			70	70 % 265/70R/18 SIZE: 70 % 265/70R/18 SIZE:								☐ TOW PACKAGE		
TRE	P FRONT	P FRONT P REAR					70 % 265/70R/18 SIZE: 70 % 265/70R/18 SIZE:									Bed Lin Tool Bo		
	SPARE						% SIZE:									1001 20	^	
	WINDSHIELD D FRONT DOOR			\boxtimes														
D FRON				\boxtimes														
GL/	P FRONT DOOR																	
	P REAR PANEL REAR WINDOW				\mathbb{R}										\exists			
_∝ DASH		NEI 0		\boxtimes														
RIO	DOOR PA	MELS		\boxtimes			Driver seat torn											
INE	CARPET																	
HEADLIN		ER	GD	FR			N/A	N/A COMMENTS:										
_	ENGINE				\boxtimes	UKN			od knock									
MECHANICAL	_	TRANSMISSION CLUTCH BRAKES FRONT END																
	BRAKES			\boxtimes														
F.																		
Ž	REAR EN BATTERY				\parallel													
COMMENTS: Mileage unverifed. Should not be driven until engine is fixed.																		
	05/21/2024																	
	EMI	PLOYEE'S FUL By si					nformation	n contai	DATE ned within th	is report to	be tru	ue and accura	EMI te to the best	PLOYEE'S of my knowle				<u></u> ,