RTR Services Inc. DUMP TRUCK CONDITION REPORT						(9, 9)					RTR UMBE	419						
YEAR: 2015			MILES 398,370						ACCOUNT NAME: VIN#: 1M2AX07CXFM023962									
MAKE:		Mack		GV	GVW:		10	BED HEI	GHT		BED LE	NGTH	17ft	BED \	WIDTH			
MODEL:		GU713		WHEELB		ASE:				COLOR: I		XTERIOR:		INTER	RIOR:		Black	
ENGINE:		Mack MP8 12.7L		HP	HP 505				KE	EYS: IGNITION: 🛛 YES 🗌			• DOOR:		X YES 🗌 NO			
т	RANS:	Alison Autor	natic	FU	FUEL:			DIESEL	-		ESTED: 🛛 YES 🗌 NO		RATI		_			
DOES MOTOR		OTOR RUN?						IT BE DRIV		1				MAGE?	AGE? 🗌 YI			
PHYSICAL APPEARANCE																		
		GD	FR	PR	N//	4	COMMENT	S					_			IONS		
ВОДҮ	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS			\boxtimes			-								PWR S AKES	TEE	RING	
				\boxtimes														
				\boxtimes)		
	GRILL	NT FENDER		\boxtimes										\square	PWR L PWR W			
	D DOO		\boxtimes			-								PWR S				
	D DUM		\boxtimes										\square	PWR M				
	REAR GATE			\boxtimes			. –										ITIONER SEAT D/P	
	REAR PANEL			\boxtimes			-							\square			SUSPENSION	
	P FRO		\square			-												
	P FRONT DOOR			\boxtimes										\square	HITCH		/ CB? <u>CD</u> PE	
	ТОР			\boxtimes										\square	TARP S			
TIRES	D FRONT D REAR A1 (S/D?)			\boxtimes				50 % 385/6 50 % 385/6						\square				
	D REAR A2 (S/D?) \Box		\boxtimes				50 % 385/6							TOOL				
	P FRONT			\boxtimes			ĺ	50 % 385/6	5R/2	22.5 SIZE:				FU	FUEL TANKS			
	P REAR A1 (S/D?)			\boxtimes			-	50 % 385/6 50 % 385/6						_			GAL	
	SPARE							%	SIZ						MUD F			
s	WINDSHIELD D FRONT DOOR						· -							WH				
S DFRO		WINDOW		\boxtimes											☐ ALUMINUM			
GL	P FRONT DOOR			\boxtimes)		
	MIRRO DASH	RS		\boxtimes			_	D/S hood n	nissin	ng mirror gl	ass							
R	_	PANELS		\boxtimes			i T								SPENSIC		5/D: <u>D_</u>	
ERIOR		SEAT(S)		\boxtimes														
INTE	FLOORING HEADLINER			\boxtimes			-										j	
-	DUMP		\boxtimes											LIFT/T	١G			
MECHANICAL	ENGIN	GD	FR			N	N/A COMME		NTS: knocks / may not be good				\square					
	ENGINE TRANSMISSION				\square					incons / IIId	, nor ne gr				WET K		<u>, , , , , , , , , , , , , , , , , , , </u>	
	CLUTCH																	
	DIFFERENTIALS BRAKES																	
	FRONT END																	
BATTERY/ELECTR Image: Comment diving. COMMENTS: Mileage unverified. Don't recommend driving.																		
								04/18/	2024			_				_		

4/ 18/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107