RTR Services Inc. TRAILER CONDITION REPORT										RTR #: 4023507 ACCOUNT NUMBER: ACCOUNT NAME:							
YEAR: 2021			BODY TYPE:		TYPE:	Dry Van			VIN#: 1UYVS2533M74120		12037						
MAKE: Utility				LICENSE:				s	TATE:	TAGS:		S: MN:			YR:		
MODEL: VS2DX				С	OLOR:	EXTERIOR: W		White	hite		INTERIOR:		White/Steel				
LENGTH: 53'		53'			WIDTH:		102"		HE	EIGHT: 13'6"				G	<b>65</b> ,000		
HITCH: GOOSE N		ECK	□ P	☐ PINTLE ⊠ 5 <sup>T</sup>		WHEEL PIN 17		1 7/8" B	ALL	☐ 2" BALL ☐ 2 5/16" B		۱LL					
IS IT ROAD READY?   ☑ YES					□ NO		COLI	ISION DA	MAGE?	☐ YE	S 🛭 N	Ю	KEYS	:	☐ YES	⊠ NO	
							F	PHYSICAL	APPEAR	ANCE							
			GD	FR	PR	N/A		MENTS						OPTIONS			
HITCH D SIDE SIDE D REAR REAR P SIDE REAR TOP		DOOR (S) PANEL BUMPER					Dent								SPRING AIR BRA ELECTRI HYD BRA SLIDER BEELS BUD SPOK	☐ BUD ☐ SPOKE	
INTERIOR	CEILING						Dent/hole								SPARE TIRE RACK REFIGERATION UNIT REEFER HRS		
TIRES	D REAR A1 (S/D?) ☐ [ D REAR A2 (S/D?) ☐ [						% SIZE:       □ TOOL BOX         % 20 SIZE: 295/75R/22.5       □ MUD FLAPS         % 20 SIZE: 295/75R/22.5       □ ROLL UP RI         % SIZE:       □ LOADING R         % SIZE:       □ BATTERY         % 20 SIZE: 295/75R/22.5       □ SIDE SKIRT         % 20 SIZE: 295/75R/22.5       □         % SIZE:       □         % SIZE:       □							APS PREAR DOOR GRAMP Y			
			GD	FR	PR	UKN	N/A	COMMI	ENTS:					l П			
WEFRICA LANDII AIR HO		GHTS L LIGHTS ANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL															
COMMENTS: Dent/damage/hole on front & passenger front outside and inside.																	
		EMDI OVERIO EIII.	NABET '	DI FAC	E DDIATE		06	5/05/2024 DATE	1			Pay-	PLOYEE'S SIG	DIAT!	DE		
		EMPLOYEE'S FULI By sig	•			certify all info	ormation c		n this report	o be true a	and accurate to						