RTR Services Inc. TRAILER											RTR #: 4023820						3		
CONDITION REPORT YEAR: 2005					BODY	TVDE	Flatbed			ACCOUNT NAME VIN#: 1C92F48285N					104.94				
MAKE: Chaparral			BODY TYPE:		Talbeu		STATE:		C92F48285M949181 TAGS: MN:					YR:					
MODEL:					OLOR:	EXTERIOR:			OTATE:			INTERIOR:				TIK.			
LENGTH: 48'				WIDTH:					HEIGHT:			ii ti Zitioiti		GVW : 90,000					
HITCH: GOOSE N		ECK	P	☐ PINTLE ☑ 5 Th		WHEEL PIN 17			7/8" BALL		□ 2"			ALL	ALL				
IS IT ROAD READY? 🛛 YES					□ NO		COLLISION DAMA			GE? ☐ YES 🖾 N			⊠ NC)	KEYS):	☐ YES	□ №	
							ŀ	PHYSICAL	ΑP	PEAR	ANCE								
	FRONT PANEL		GD	FR	PR	N/A	COMMENTS											TIONS	
TIRES INTERIOR BODY	HITCH D SIDE PANEL SIDE DOOR (S) REAR PANEL REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A2 (S/D?)						% 90 % 90 % % % 90 % 90	% 90 SIZE: 295/751 % 90 SIZE: 295/751 % SIZE: % SIZE: % 90 SIZE: 285/751 % 90 SIZE: 285/751									SPRING AIR BRA ELECTR HYD BR SLIDER SLIDER SPON STEE ALUN LIFT/TA SPARE REFIGE REEFER TOOL B MUD FL ROLL U LOADIN		
				\boxtimes			☐ % 90 SIZE: 11R24.5												
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO	GHTS L LIGHTS LANCE LGT R AXLES GERATION NG GEAR DSE/GLAD R PIGTAIL	GD		PR		N/A	COMMI	ENT	'S:									
COMMENTS: P/S latch is warped on the tool box, it will not close properly.																			
02/16/2024																			
EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.																			