RTR Services Inc. HEAVY TRUCK CONDITION REPORT		RTR #:	4023912
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2019	MILES	565,979	VIN#:	3HSDZAPR2KN409653						
MAKE:	International	GVW:		LICENSE:		ST:		TAGS:	MONTH		YR:
MODEL:	LT625	WHEELBASE:	228	COLOR: EXTERIOR:	Green	INTERIOR:	Gray				
ENGINE:	Cummins X15	HP		BODY TYPE:	Sleeper	KEYS: IGNITION: ☒ YES ☐ NO • DOOR: ☒ YES ☐ NO					
TRANS:	10 Speed	FUEL: ☐ GAS ☒ DIESEL		ANTIFREEZE TESTED: ☐ YES ☒ NO		RATING:					
DOES MOTOR RUN?	☐ YES	☒ NO	CAN IT BE DRIVEN?	☐ YES	☒ NO	COLLISION DAMAGE?	☐ YES	☒ NO			

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT BUMPER	☐	☐	☒	☐	Cracked, held on with bungee cord
	HEAD LIGHTS	☐	☒	☐	☐	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☒	☐	☐	
	GRILL	☐	☒	☐	☐	
	D FRONT FENDER	☐	☒	☐	☐	Scratched
	D DOOR	☐	☒	☐	☐	
	D SLEEPER	☐	☒	☐	☐	
	REAR BUMPER	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☒	☐	☐	
	REAR PANEL	☐	☒	☐	☐	
	P FRONT FENDER	☐	☒	☐	☐	
	P FRONT DOOR	☐	☒	☐	☐	
	P SLEEPER	☐	☒	☐	☐	
	TOP	☐	☒	☐	☐	
TIRES	D FRONT	☐	☒	☐	☐	35 % 11R 22.5 SIZE:
	D REAR A1 (S/D?)	☐	☒	☐	☐	35 % 11R 22.5 SIZE:
	D REAR A2 (S/D?)	☐	☒	☐	☐	35 % 11R 22.5 SIZE:
	P FRONT	☐	☒	☐	☐	35 % 11R 22.5 SIZE:
	P REAR A1 (S/D?)	☐	☒	☐	☐	35 % 11R 22.5 SIZE:
	P REAR A2 (S/D?)	☐	☒	☐	☐	35 % 11R 22.5 SIZE:
	SPARE	☐	☐	☐	☒	% SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	D FRONT DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☐	☐	☒	
	P FRONT DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☒	☐	☐	
INTERIOR	DASH	☐	☒	☐	☐	
	DOOR PANELS	☐	☒	☐	☐	
	SEAT(S)	☐	☒	☐	☐	
	CARPET	☐	☐	☐	☒	Ripped
	HEADLINER	☐	☒	☐	☐	
	SLEEPER	☐	☒	☐	☐	

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☐	☒	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☒	☐	
	DIFFERENTIALS	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☒	☐	☐	
	REAR END	☐	☐	☒	☐	☐	
	BATTERY/ELECTR	☐	☐	☒	☐	☐	Dead. Needs new battery box and cover

OPTIONS
☒ PWR STEERING
BRAKES
☒ AIR
☐ HYD
☒ PWR LOCKS
☒ PWR WINDOWS
☒ PWR SEATS
☐ PWR MIRRORS
☒ AIR CONDITIONER
☐ AIR RIDE SEAT D/P
☐ AIR RIDE SUSPENSION
☐ CONV. 5TH WHEEL
☐ SLIDING 5TH WHEEL
☒ AM FM RADIO
☒ TAPE / CD / CB? CD
☒ SLEEPER SIZE? _____
☒ ELECTRICAL PIGTAIL
☒ GLAD HANDS
FUEL TANKS
☐ SINGLE GAL _____
☒ DUAL GAL _____
☒ MUD FLAPS
WHEELS
☒ ALUMINUM
☐ STEEL
☐ BUD
☐ SPOKE
☐ EXHAUST S/D? _____
SUSPENSION
☒ AIR
☐ SPRING
☐ PAD
☒ TANDEM AXLE
☒ ENGINE BRAKE
☐ TOOL BOX
☐ LIFT/TAG AXLE
☐ WET KIT
☐
☐
☐
☐
☐

COMMENTS: Mileage unverified. Reported to need a new driveshaft which caused damage to the surrounding area.

02/27/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107