RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	4033350
		ACCOUNT NUMBER:	
		ACCOUNT NAME:	

YEAR:	2014	VIN/SN:	2341499				
MAKE:	Tigercat	☒ WHEEL ☐ TRACK ☒ STATIONARY ☐ SKIDMOUNTED					
MODEL:	234	COLOR: EXTERIOR:	Yellow	INTERIOR:	Black		
ENGINE:	QSB6.7 Tier III	HP:	173	KEYS: IGNITION: ☐ YES ☐ NO ☒ N/A • DOOR: ☒ YES ☐ NO ☐ N/A			
TRANS:	Hyd	FUEL: ☒ DIESEL ☐ GAS ☐ PROPANE ☐ CNG ☐ ELECTRIC ☐ HYDRAULIC					
HRS:	12,298	DOES IT RUN?	☐ YES	☒ NO	☐ UNK	CAN IT BE DRIVEN?	☐ YES ☒ NO ☐ UNK
		LENGTH:	40'	WIDTH:	8.5'	HEIGHT:	WEIGHT:

PHYSICAL APPEARANCE

		GD	FR	PR	N/A	COMMENTS
BODY	FRONT	☐	☒	☐	☐	
	HEAD LIGHTS	☐	☐	☐	☒	
	HOOD	☐	☒	☐	☐	
	TURN SIGNALS	☐	☐	☐	☒	
	GRILL	☐	☒	☐	☐	
	L FRONT FENDER	☐	☒	☐	☐	
	L DOOR	☐	☒	☐	☐	
	L REAR PANEL	☐	☒	☐	☐	
	SAFETY LIGHTS	☐	☐	☐	☒	
	REAR	☐	☒	☐	☐	
	TAIL LIGHTS	☐	☐	☐	☒	
	FRAME	☐	☒	☐	☐	
	TURN SIGNALS	☐	☐	☐	☒	
	R FRONT FENDER	☐	☒	☐	☐	
	R FRONT DOOR	☐	☒	☐	☐	
	R REAR PANEL	☐	☒	☐	☐	
	WORK LIGHTS	☐	☐	☐	☒	
	TOP	☐	☒	☐	☐	
TIRES	L FRONT	☐	☐	☒	☐	20 % 11R22.5 SIZE:
	L REAR	☐	☐	☒	☐	20 % 11R22.5 SIZE:
	R FRONT	☐	☐	☒	☐	20 % 11R22.5 SIZE:
	R REAR	☐	☐	☒	☐	20 % 11R22.5 SIZE:
GLASS	WINDSHIELD	☐	☒	☐	☐	
	L DOOR	☐	☒	☐	☐	
	REAR WINDOW	☐	☒	☐	☐	
	R DOOR	☐	☒	☐	☐	
	MIRRORS	☐	☐	☐	☒	
INTERIOR	DASH/GAUGES	☐	☐	☐	☒	
	DOOR PANELS	☐	☐	☐	☒	
	SEAT	☐	☒	☐	☐	
	CARPET/MAT	☐	☐	☒	☐	
	CONTROLS	☐	☒	☐	☐	

OPTIONS	
☐	PWR STEERING
☐	PWR BRAKES
☒	ENCLOSED CAB
☒	TINTED GLASS
☐	AIR CONDITIONER
☐	HEATER
☐	AIR RIDE SEAT
☐	AIR RIDE SUSPENSION
☒	AM FM RADIO
☐	TAPE DECK
☒	CD PLAYER
☐	MUD FLAPS
☐	2WD
☐	4WD
☐	PTO
☐	BLADE
☐	BUCKET SIZE _____
☐	RIPPER _____
☐	ROLLER _____
☐	COMPACTOR _____
☐	BOOM _____
☐	TRENCHER _____
☐	SCRAPER _____
☐	TRACK WIDTH _____
☐	GENERATOR
	VOLTS _____
	WATTS _____
☐	COMPRSR CFM _____
☐	TANK SIZE GAL _____
☐	HITCH _____
☐	ROP
☐	FUEL TANKS _____
☐	AUXILIARY HYDS

		GD	FR	PR	UKN	N/A	COMMENTS:
MECHANICAL	ENGINE	☐	☐	☐	☒	☐	
	TRANSMISSION	☐	☐	☐	☒	☐	
	CLUTCH	☐	☐	☐	☐	☒	
	DIFFERENTIAL	☐	☐	☐	☐	☒	
	2ND DIFFERENTIAL	☐	☐	☐	☐	☒	
	UNDERCARRIAGE	☐	☐	☐	☒	☐	
	BRAKES	☐	☐	☐	☒	☐	
	FRONT END	☐	☐	☐	☒	☐	
	REAR END	☐	☐	☐	☒	☐	
	BATTERY/ELECTR	☐	☒	☐	☐	☐	Batteries Replaced 05/20

COMMENTS: Hours unverified. Does not start. Paint chips and scratches throughout.

05-17-2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107