RTR Services Inc. TRAILER											RTR #: 4033616 ACCOUNT NUMBER:								
CONDITION REPORT YEAR: 2022				BODY	- O				ACCOUNT NA				40040						
YEAR: 2022 MAKE: DeLucio				BODY TYPE: LICENSE:		Dry Van			VIN#: STATE:		76403007		23ND010040 TAGS: MN:				YR:		
MODEL: D500				COLOR:		EXTERIOR: W		w	hite				INTERIOR:		White/Steel/Wood				
LENGTH: 53'				WIDTH:		102"		-			13'6	13'6"		GVW: 80,000					
		☐ GOOSE N	ECK	ПР] 1 7			☐ 2" BALL		☐ 2 5/16" BA		,			
IS IT ROAD READY? ⊠ YES			s	□ NO		COLLISION DAMA			GE?	☐ YE		⊠ NC	IO KEYS		:	☐ YES	⊠ NO		
PHYSICAL APPEARANCE																			
			GD	FR	PR	N/A	COMI	MENTS									OPT	TIONS	
TIRES INTERIOR BODY	REAR DOOR (S) P SIDE PANEL REAR BUMPER TOP FLOOR D SIDE PANELS FRONT PANEL P SIDE PANEL CARGO RAILS CEILING D FRONT D REAR A1 (S/D?) D REAR A3 (S/D?)		000000000000000000000000000000000000000				% SIZE: % 20 SIZE: % 20 SIZE: % SIZE: % SIZE: % SIZE: % SIZE: % 20 SIZE: % 20 SIZE: % 20 SIZE:										AIR RIDE SUSPENSION SPRING SUSPENSION AIR BRAKES ELECTRICAL BRAKES HYD BRAKES SLIDER AXLE WHEELS BUD SPOKE STEEL ALUMINUM LIFT/TAG AXLE SPARE TIRE RACK REFIGERATION UNIT REEFER HRS TOOL BOX MUD FLAPS ROLL UP REAR DOOR LOADING RAMP BATTERY		
			GD	FR	PR	UKN	% N/A	SIZE:	CNIT	IC.									
MECHANICAL	CLEAR SLIDEF REFRIC LANDII AIR HO	GHTS L LIGHTS LANCE LGT R AXLES GERATION NG GEAR PSE/GLAD R PIGTAIL						COMM	DIN I	5.									
COMMENTS: Missing inside tires and wheels on all four sets.																			
04/22/2024																			
		EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.																	