

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 4033870	
YEAR:	2001		
MAKE:	Excel	<input checked="checked" type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	EX-62	<input type="checkbox"/> OPERATIONAL	
SN:	EX2232	<input type="checkbox"/> NON OPERATIONAL	
POWER:	20 Hp	<input checked="checked" type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Excel Full Penetration Horizontal Baler Model EX-62		
SHOT / COUNT / HOUR: 9,823			
NOTES / COMMENTS: Hours unverified. Unable to test operability. Appeared to have been in use upon pickup.			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	
YEAR:			
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		<input type="checkbox"/> OPERATIONAL	
SN:		<input type="checkbox"/> NON OPERATIONAL	
POWER:		<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	
YEAR:			
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		<input type="checkbox"/> OPERATIONAL	
SN:		<input type="checkbox"/> NON OPERATIONAL	
POWER:		<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			

6/7/2024

_____	_____	_____
EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.		