RTR Services Inc. BOX TRUCK CONDITION REPORT										RTR #: 4043159 ACCOUNT NUMBER: ACCOUNT NAME:								
YEAR: 2017			MIL	MILES 420,741				VIN#: 1HTMMML3HH511610										
MAKE: International			GV	GVW:			BOX HEIGHT			BOX LENGTH 26'		BOX WIDTH						
MODEL: 4000			WH	WHEELBASE:				-		OR: EXTERIOR: White			INTERIOR: Gray					
ENGINE: B 6.7L. Cummins			HP						EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR: 🛛				: 🛛 YE					
TRANS: Automatic			FUEL: GAS											RATING:				
	DOES M	OTOR RUN?	🛛 YE							I? │ ⊠ YES │ □ NO │ COLLISION DAMA \L APPEARANCE					IAGE? 🗌 YES 🛛 NO			
			FR PR N/A COMMENTS						LAPPEARANCE					OPTIONS				
BODY	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS GRILL D FRONT FENDER D DOOR		GD	\boxtimes			COMIN								PWR STEERING			
				\boxtimes									BR					
				\boxtimes						<u> </u>					_ ⊠ AIR □ □ HYD			
				\boxtimes														
				\boxtimes										PWR WINDOWS PWR SEATS				
	D BOX			\boxtimes											-	IRRORS		
	REAR BUMPER TAIL LIGHTS			\boxtimes			-											
	REAR PANEL			\boxtimes										$-\Box$	AIR RIDE SEAT D/P			
	P FRONT FENDER			\boxtimes										\square	AM FM			
	P FRONT DOOR P BOX			\boxtimes									TAPE / CD / CB? □ SLEEPER SIZE?					
	TOP			\boxtimes								□ SLEEPER SIZE? □ TRANSLUCENT ROOF						
TIRES	D FRONT			\boxtimes			90 % 11R 22.5 SIZE: 90 % 11R 22.5 SIZE: % SIZE:											
	D REAR A1 (S/D?) D REAR A2 (S/D?)																	
	P FRONT			\boxtimes		90 % 11R 22.5												
	P REAR A1 (S/D?) P REAR A2 (S/D?)			\square			90 %	<u>11R 22.</u>	5 SIZE:						_	SLE GAL		
	SPARE					\boxtimes	% SIZ											
LASS	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR			\boxtimes							WHEELS							
				\boxtimes														
GL				\boxtimes											🗌 BUD			
	MIRRO DASH	RS		\boxtimes											KE ST S/D? <u>S_</u>			
æ	DOOR PANELS			\boxtimes											SPENSIO			
RIOR	SEAT(S) FLOORING			\boxtimes														
INTEI		IEADLINER		\boxtimes														
≤	SLEEP					\boxtimes									TANDE	MAXLE		
	BOX		GD	FR	PR		N/A	COMM	IENT	NTS:			ᅴ님	ENGINE TOOL B	E BRAKE SOX			
MECHANICAL	ENGIN			\boxtimes											LIFT/TA			
		TRANSMISSION CLUTCH		\square										\square	RAMP LIFT GA	ATE		
	DIFFERENTIALS BRAKES			\boxtimes														
			\Box \boxtimes	\boxtimes														
	FRONT END REAR END			\boxtimes														
_	BATTERY/ELECTR		\boxtimes					Replac	Replaced 5/2024									
REFRIGERATION Image: Image line line line line line line line lin																		
<u> </u>																		
							04	/23/202	24									

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107