	RTR S	Services Inc	: .								RTR #: 4043176						6				
HEAVY TRUCK										ACCOUNT NUMBER:											
		TION REPO	RT		ر)						ACCOUNT NAME:										
YEAR:		2018		MI	LES	675,80)7			VIN#	#: 4	V4NC9EH	5JN895	431							
MAKE:		Volvo		G۱	GVW:		LICEN	NSE:				ST:		TAGS:	МО	NTH		`	YR:		
MODEL:		VNL64 T780		WI	WHEELBASE:				COLOR:		R: E	EXTERIOR: Green		en	INTE						
ENGINE:		Volvo D13		HP	HP 425		BODY TYPE:		Slee	eper		KEYS:	GNITION: X YES		S 🗆 N] NO • DC		OOR: X YES NO			
TRANS:		Automatic Trans.		FU	EL:	GAS		L	ANTIFREEZE		ZE TI	TESTED: 🛛 YES 🗌 N		NO	RA	ATING:		-10			
DOES N		OTOR RUN? 🛛 YES		S NO) (CAN IT BI					□NO	COLLISION DAM		AMAG	E?	□ Y	ES	⊠N	0	
PHYSICAL APPEARANCE																					
ВОДУ		DUMBER	GD	FR	PR	N/A		COMMENTS										OPTIC			
	_	BUMPER		\boxtimes			Crack	Crack in front													
	HOOD	2101110			$ \Box$										- '	⊠ AIR					
	TURN SIGNALS			\boxtimes												☐ HYD					
	GRILL				무	$\perp \Box$													_		
	D FRONT FENDER D DOOR			\boxtimes												☑ PWR WINDOWS☑ PWR SEATS					
	D SLEE	H		ΙH	ΙH	Plasti	Plastic cracked on rear step behind sleeper								_		MIRR	-			
	REAR		\boxtimes				Staditod on roal otop bolinia dicopol										ONDI		ER .		
	TAIL LIGHTS															_		IDE S			
	REAR PANEL P FRONT FENDER				믐											_		IDE S '. 5™ \		NSION	
	P FRONT DOOR				lΗ													NG 5 ^T			
	P SLEEPER			\boxtimes														M RAI			
	TOP				$\vdash \Box$	$\perp \Box$	40	0/ 005										/ CD			
	D FRONT D REAR A1 (S/D?)			\boxtimes			40/40	% 295 % 295										PER S		STAIL	
တ	D REAR A2 (S/D?)			\boxtimes	$ \; \exists \;$			% 295										HAN)	
TIRES	P FRONT			\boxtimes			40	% 295	/75R	22.5 S	IZE:				F	UEL	TAN	KS			
	P REAR A1 (S/D?)							% 295										NGLE			
	P REAR A2 (S/D?) SPARE						40/0	% 295 %		22.5 S SIZE:	olZE:				— г			IAL G			
SS	WINDSHIELD				H			70		,1 <u>2</u> L.						MHE!	_	LAI	•		
	D FRONT DOOR			\boxtimes												_	_	UMIN	UM		
GLA	REAR WINDOW P FRONT DOOR																_ ST _ BU				
0	_	MIRRORS			lΗ	$\mid \; \exists \;$											_ BU _ SP				
	DASH																	UST	S/D? §	<u>3_</u>	
OR	DOOR PANELS SEAT(S)			\boxtimes													ENSI	_			
ERIO																	⊠ AIF				
INTE		CARPET HEADLINER														_	_ ຣ¤ ∃ PA	RING			
_	SLEEPER			\boxtimes													_	EM A	XLE		
		GD	FR	PR	UKN		COM								=		NE BF				
MECHANICAL	ENGIN			\boxtimes	ᅵ片			Igniti	on s	witch h	hard t	o turn on						BOX			
	TRANSMISSION CLUTCH																NET H		IVLE		
	DIFFERENTIALS			\boxtimes												5					
	BRAKES			\boxtimes																	
	FRONT END REAR END															$\bar{\bar{q}}$					
							rv ne	needed to be charged to start						7							
COMMENTS: Mileage Unverified.																					
							5/	15/202	24												
		EMPLOYEE'S FULL					-	DAT	ΓE					EMPLOYEE'						_	
		By sig	nature ab	ove I do	nereby	certify all	intormation c	ontained v	vithin t	nis report	t to be ti	rue and accura	ate to the b	est of my kno	wledge a	at prese	ent.			_	