

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #: 4043675	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:	2022		
MAKE:	Atlas	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:	Copco Airpower	<input checked="" type="checkbox"/> OPERATIONAL	
SN:	YA3C1C918N086992	<input type="checkbox"/> NON OPERATIONAL	
POWER:	CPS110	<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:	Portable Air Compressor		
SHOT / COUNT / HOUR: 357			
NOTES / COMMENTS: Hours unverified.			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:			
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		<input type="checkbox"/> OPERATIONAL	
SN:		<input type="checkbox"/> NON OPERATIONAL	
POWER:		<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT		RTR #:	
		ACCOUNT	
		ACCOUNT NAME:	
YEAR:			
MAKE:		<input type="checkbox"/> YES <input type="checkbox"/> NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY
MODEL:		<input type="checkbox"/> OPERATIONAL	
SN:		<input type="checkbox"/> NON OPERATIONAL	
POWER:		<input type="checkbox"/> UNTESTABLE	
DESCRIPTION:			
SHOT / COUNT / HOUR:			
NOTES / COMMENTS:			

4/30/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT)	DATE	EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.		