RTR Services Inc. TRAILER CONDITION REPORT											RTR #: 404 ACCOUNT NUMBER: ACCOUNT NAME:					2				
YEAR: 2010			BODY	TYPE:	Dry Van			VIN#: 1UYVS253				96226								
MAKE:		Utility	ility			ENSE:				STATE:				TAGS: MN:			YR:			
MODEL: Se		Semi	i		COLOR:		EXTERIOR: W		W	/hite			INTERI		TERIOR:	W	/hite/Wood/Steel			
LENGTH: 53'					VIDTH:	102"			HEIGHT: 1		13	13'6"			0	GVW: 65,000		0		
			🗌 PI	NTLE	⊠ 5™				7/8" BALL 🔲 2" BALL				2 5/16" B/	ALL						
IS IT ROAD READY?			S	NO 🛛		COLLISION DAMA PHYSICAL AP						0	KEYS	5 :		5	🛛 NO			
									AP	PEARAI	NCE									
BODY	FRONT	PANEL	GD	FR	PR	N/A	COMN	IENTS							OPTIONS					
	нтсн			\boxtimes										SPRING SUSPENSIO						
	SIDE DOOR (S) REAR PANEL REAR DOOR (S)			\square										AIR BRAKES ELECTRICAL BRAKES HYD BRAKES						
				\square		\square												=		
					□ □ Missing rear doors								\boxtimes							
			\boxtimes											WHEELS						
INTERIOR			\boxtimes																	
	D SIDE PANELS		\boxtimes																	
	P SIDE PANEL		\boxtimes													SPARE	TIR	E RACK		
	CARGO RAILS		\square		\square									REFIGERATION UNIT						
TIRES						%	SIZE:									TOOL				
	D REAR A1 (S/D?)			\boxtimes		% 0 SIZE:								MUD FLAPS ROLL UP REAR DOOR						
	D REAR A2 (S/D?)			\square		\square	% 50 %	SIZE: SIZE:									LOADI			२
	P FRONT					\boxtimes	%	SIZE:									BATTE			
	P REAR A1 (S/D?)				\square			% 0 SIZE:												
	P REAR A2 (S/D?) P REAR A3 (S/D?) SPARE			\square		\square	% 50 SIZE: % SIZE:													
						\boxtimes	⊠ % SIZE:													
ECHANICAL	TAIL LIGHTS		GD	FR	PR		N/A	COMMI	ENT	'S:										
	SIGNAL LIGHTS CLEARANCE LGT SLIDER AXLES REFRIGERATION			\boxtimes																
				\boxtimes																
CHA							\square													
ME							Missing pad			ds										
				\boxtimes																
COMMENTS: Front axle on trailer is bent.																				

05/02/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 395 Market St. NE Salem OR 97301 • 1.800.238.3294 • FAX 503.399.0421

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107