RTR Services Inc.										RTR #: 4051549						9					
		TRUCK	ОΤ		CD THE		_					UNT NU									
CONDITION REPOR			ΚI	MIL	Ť	Ť				VIN#: 54DB4W1B3CS804958											
MAKE: Isuzu				GV			12,000lb BOX HEI								B	BOX WIDTH					
MODEL: NPF						BASE:				COLOR: EXTERIOR: White						INTERIOR: Gray					
)L V-8	/_R			AGE.			KEYS: IGNITION: ⊠ YES ☐ NO • DOOR:												
TRANS: Automatic				HP	FI · C	 ☐ GAS ⊠ DIESEL								_	RATING:						
			⊠ YE		□ NO											J. ∏YE	s	NO NO			
	DOLO MOTO	on non:					AITH			L APPEARANCE			IOIOIV DA		JE .						
			GD	FR	PR	N/A	COI	MMENTS									(OPTI	ONS		
ВОДУ	FRONT BUMPER HEAD LIGHTS HOOD TURN SIGNALS			\boxtimes				ken							✓ PWR STEERINGBRAKES✓ AIR						
				$\boxtimes\boxtimes\boxtimes$			Fad	ed													
																⊠ HYD					
	GRILL FENDER															_	PWR L				
	D FRONT FENDER D DOOR			\boxtimes												_	PWR W PWR S				
	D BOX		\boxtimes			Den	ted panel	l								PWR M					
	REAR BUN		\boxtimes												=			ΓΙΟΝER EAT D/P			
																			USPENSIO	ON	
	P FRONT FENDER							41								_	AM FM		-		
	P BOX	P FRONT DOOR [[P BOX []		\boxtimes			Den	Dented									SLEEP		CB? <u>CD</u> IZE?	-	
	TOP															TRANS	LUC	ENT ROO	F		
TIRES	D FRONT D REAR A1 (S/D?)							% 215/8R 10 % 215/								=	E-TRAC BOX DO				
	D REAR A2 (S/D?)						10/	% % % % % % % % % % % % % % % % % % %		SIZE:							SIDE D	_	_		
	P FRONT [% 215/8R									L TANK		0.41		
	P REAR A1 (S/D?) P REAR A2 (S/D?)						10/1	0 % 215/ %		6 SIZE: SIZE:						⊠ SINGLE GAL □ DUAL GAL					
	SPARE				\boxtimes		% SIZE:								⊠ MUD FLAPS						
LASS	WINDSHIELD D FRONT DOOR REAR WINDOW P FRONT DOOR						Cra	cked									ELS ALU	IMINI	I IN		
															□ STE		Olvi				
ß													□ BUD □ SPOKE								
	MIRRORS DASH																	S/D? S			
~	DOOR PAN																				
RIOR	SEAT(S)						Wo	Worn/torn					☐ AIR ⊠ SPR	ING							
INTERI	FLOORING HEADLINER			\boxtimes																	
_	SLEEPER					\boxtimes			drivers side corner							_	TANDE				
	ВОХ	GD	⊠ FR	PR	UKN	Hol-				r					_	ENGINI TOOL I					
MECHANICAL	ENGINE		\boxtimes													LIFT/T					
		TRANSMISSION														_	RAMP LIFT G	^ T E			
		CLUTCH DIFFERENTIALS															LIFT G	AIE			
	BRAKES			\boxtimes																	
	FRONT END			\boxtimes																	
	BATTERY/ELECTR																				
CO	REFRIGER		(orified	Tho:		rest de	or is v	ory diffic	ult t	o onen ana	4 ^	loca I if	nate de	en't wor	·k m	oter '	likaly b	ad P	ov actima	atod	
COMMENTS: Mileage unverified. The roll up rear door is very difficult to open and close. Lift gate doesn't work, motor likely bad. Box estimated to be 16'.																					
	8/7/2024																				
	EMPL	LOYEE'S FULI					_	DAT	ΓE		-			MPLOYEE'S							
		By sig	gnature abo	ove I do	nereby	certify all in	ιτormatio	n contained w	vitnin t	his report to be	e tru	ie and accura	ate to the be	st of my knov	wiedge	at pre	sent.				