RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #: ACCOUNT ACCOUNT NAME:	4051860		
YEAR:	2004					
MAKE:	Peterson	🖾 YES 🗌 NO	EQUIPMENT WAS IN USE AT THE TIME OF R	ECOVERY		
MODEL:	2400B	Ø OPERATIONAL				
SN:	17B-177-842					
POWER:		UNTESTABLE				
DESCRIPTION:	Horizontal Grinder					
SHOT / COUNT / H	SHOT / COUNT / HOUR: 113					
NOTES / COMMENTS: Hours unverified.						

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #: ACCOUNT ACCOUNT NAME:		
YEAR:					
MAKE:		🗌 YES 🗌 NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:					
SN:					
POWER:					
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMME	NTS:				

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT			RTR #: ACCOUNT ACCOUNT NAME:		
YEAR:					
MAKE:		YES NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:					
SN:					
POWER:					
DESCRIPTION:					
SHOT / COUNT / H	HOUR:				
NOTES / COMMENTS:					

9/25/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE
By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107