RTR Services Inc. FORKLIFT					Fair			RTR #: 405301					
					n V 💓		ACCOUNT NUMBER	ACCOUNT NUMBER:					
CONDITION DEPOST						10	A COOLINIT NIA BAT	ACCOUNT NAME.					
CONDITION REPORT				ACCOUNT NAME:									
YEAR: 2014				VIN/S	N· I	DHW012	30	CAPACI	TY.	12,000lbs			
MAKE: CAT								_	07117101		12,000.00		
		TL1255C				COLOR: EXTERIOR: Yellow INTERIOR: Black							
ENGINE: CAT				KEYS: IGNITION: YES □ NO □ N/A • DOOR: YES □ NO □ N/A									
TRANS: Automatic					FUEL: DIESEL GAS PROPANE ELECTRIC								
HRS: 2,432					DOES IT RUN? YES NO UNK CAN IT BE DRIVEN?						YES NO [UNK	
PHYSICAL APPEARANCE													
			GD	FR	PR	N/A	COMM	ENTS			OPTIONS		
-	FRONT HEAD LIGHTS HOOD TURN SIGNALS GRILL		<u> </u>	\boxtimes] 🛛	PWR STEERING	ì	
											PWR BRAKES ENCLOSED CAR		
											TINTED GLASS	5	
											AIR CONDITION	ER	
	L FRONT FENDER					\boxtimes				\boxtimes	HEATER		
	L DOOR			\boxtimes							AIR RIDE SEAT		
ВОDУ	L REAR PANEL SAFETY LIGHTS										AM FM RADIO TAPE DECK		
BO	REAR		Ħ		H					H	CD PLAYER		
	TAIL LIGHTS					\square					MUD FLAPS		
	FRAME									2WD			
					\Box						4WD CUSHION TIRES	2	
	R FRONT DOOR		Ħ		1 🗂						PNEUMATIC TIR		
	R REAR PANEL					\boxtimes					MAST HEIGHT		
	WORK LIGHTS										MAX MAST HT	5 011	
	TOP L FRONT				$\frac{1}{1}$		50 % 1	7.5-25 SIZE:			TILT ANGLE FORK LENGTH	50" 48"	
S	L REAR		H		1 🗟			7.5-25 SIZE:			FORK WIDTH		
TIRES	R FRONT			\boxtimes				7.5-25 SIZE:			REACH LIFT		
_	R REAR					50 % 1	7.5-25 SIZE:			SIDE SHIFT			
ဟ	WINDSHIELD L DOOR		님								FORK POSITION		
AS	REAR WINDOW R DOOR MIRRORS		H								PUSH-PULL UNI		
GLA						\square					FORK EXTENSION		
										\boxtimes	HITCH		
굕	DASH/GUAGES DOOR PANELS			\boxtimes							ROP CHARGER		
DOOR PA SEAT CARPETA		MELS				H	Well used					FRS	
		MAT					Won dood				THOM OTABLE	LINO	
CONTROLS			\boxtimes										
	ENCINE		GD	FR	PR	UKN	N/A	COMMENTS:					
	ENGINE TRANSMISSION		\exists	\boxtimes						H			
MECHANICAL		CLUTCH											
$\frac{9}{8}$	DIFFERI				\boxtimes			Front diff needs repairs					
¥		2 ND DIFFERENTIAL					IН			님			
E	2 ND DIFFERENTIAL									ᅢ			
Σ										H			
			fied. R	ight r	ear tire	felt low	. The fro	nt drive shaft is removed and in cab due	to the diffe	renti	ial issue. Tires are	dry	
rott	rotted but still hold air.												
							10/1	1/2024					

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

EMPLOYEE'S SIGNATURE

DATE

EMPLOYEE'S FULL NAME (PLEASE PRINT)

