RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	4053019
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:	2020				
MAKE:	Carlton	☐ YES ☒ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:	SP5014	☒ OPERATIONAL			
SN:	1J9BA3218L1167363	☐ NON OPERATIONAL			
POWER:	Gas	☐ UNTESTABLE			
DESCRIPTION:	Self Propelled Stump Grinder				
SHOT / COUNT / HOUR: Hours 255					
NOTES / COMMENTS:					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

RTR Services Inc. GENERAL EQUIPMENT CONDITION REPORT				RTR #:	
				ACCOUNT	
				ACCOUNT NAME:	
YEAR:					
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY		
MODEL:		☐ OPERATIONAL			
SN:		☐ NON OPERATIONAL			
POWER:		☐ UNTESTABLE			
DESCRIPTION:					
SHOT / COUNT / HOUR:					
NOTES / COMMENTS:					

5/24/24

EMPLOYEE'S FULL NAME (PLEASE PRINT) | DATE | EMPLOYEE'S SIGNATURE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107