RTR Services Inc. BOX TRUCK										RTR #: 4053328 ACCOUNT NUMBER:						
CONDITION REPORT YEAR: 2020			MII	ES	15,811	0		ACCOUNT NAME: VIN#: 4UZAC2EA8LCLT0699								
MAKE: Freigtliner					19,500						BOX	BOX WIDTH 8'				
MODEL: MT45G			WH	WHEELBASE:				COLOR:	EXTERIOR:	DR: White		INTE	INTERIOR: Gray			
ENGINE: V8 6.0L			HP	308	3		K	EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR: 🛛				R: 🛛 YE				
TRANS: Automatic			FU	EL: 🖂	GAS	DIESEL		NTIFREEZE TESTED: VES NO			RATI	RATING:				
DOES MOTOR RUN? 🛛 YES			S [CAN IT BE DRI					AMAGE	MAGE? 🛛 YES 🛛 🖾 NO				
									LAPPEARANCE					OPTIONO		
BODY	FRONT BUMPER		GD	FR PR		N/A	COMMENTS						OPTIONS			
	HEAD LIGHTS HOOD TURN SIGNALS			\bowtie									BRAKES			
				\boxtimes									□ AIR ⊠ HYD			
	GRILL			\boxtimes										PWR LO	скѕ	
	D FRONT FENDER D DOOR			\boxtimes									$\exists \exists$	PWR WI		
	D BOX			\boxtimes										PWR MI		
	REAR BUMPER TAIL LIGHTS			\boxtimes												
	REAR PANEL			\boxtimes											E SEAT D/P E SUSPENSION	
	P FRONT FENDER			\boxtimes											-	
	P FRONT DOOR P BOX			\boxtimes									-	SLEEPE	:D / CB? R SIZE?	-
	TOP			\boxtimes									\square		UCENT ROOF	•
TIRES	D FRONT D REAR A1 (S/D?)			\boxtimes					19.5 SIZE:)R/19.5 SIZ	-				□ E-TRACK LINING □ BOX DOME LIGHT		
	D REAR A2 (S/D?)					\boxtimes	%	% SIZE:								
	P FRONT P REAR A1 (S/D?)			\boxtimes						9.5 SIZE:			FU	FUEL TANKS SINGLE GAL		
	P REAR A2 (S/D?)					\boxtimes		40/40 % 225/70R/19.5 SIZE: % SIZE:								
		SPARE WINDSHIELD			<u> </u>		%	SI	ZE:					MUD FL/ IEELS	APS	
ŝ	D FRONT DOOR			\boxtimes									V		IINUM	
LAS:	REAR WINDOW			\boxtimes											L	
G		P FRONT DOOR MIRRORS													Æ	
	DASH	DASH		\boxtimes										EXHAUS	T S/D?	
RIOR	DOOR PANELS SEAT(S) FLOORING			\boxtimes			Torn							SPENSION	4	
ш															NG	
INT	HEADLINER SLEEPER													□ PAD □ □ TANDEM AXLE		
	BOX			\square										ENGINE		
	ENCIN	GD	FR	FR PR UI		N/A	COMME	IENTS:				TOOL BO				
Ļ		ENGINE TRANSMISSION		\boxtimes								$\exists \exists$	LIFT/TAC RAMP	JAALE		
MECHANICAL	CLUTCH						\boxtimes							LIFT GA		
	DIFFERENTIALS BRAKES			\boxtimes									\square	Shelving	I	
	FRONT END			\boxtimes												
	REAR END BATTERY/ELECTR			\boxtimes												
	REFRIGERATION															
COMMENTS: Mileage unverified. Driver side window broken. Mirrors on driver side missing. First digit on the odometer keeps glaring in and out. Should read 15,811.														ut.		
5110		. 13,011.														
							05	/22/202	1							

5/22/2024

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107