RTR Services Inc.						IIII	$\overline{I}_{-}0$			RTR #: 405340						403	3				
DUMP TRUCK											ACCOUNT NUMBER:										
CONDITION REPORT									ACCOUNT NAME:												
YEAR: 2		2007		MIL	.ES	584,06	3			VIN#:	1	1M2AK07C67N018588									
MAKE:		Mack		GVW:		60,000)	BED HEIGHT		5'	BED LENGTH		ENGTH	14' B		BED	BED WIDTH 8'				
MODEL:		Vision CXN61	WH	IEELE	3ASE: 21		•		COLOR: EXTERIOR: White			ite				T	an				
ENGINE:		Mack AC 12.0	HP	46	0			KE	EYS: IGNITION: X YES NO • DOOR:				⊠ Y								
TRANS:		10 Speed Ma					⊠ DIE	L		TIFREEZ	ZE T	ESTED:	☐ YES [ΓING	-			
DOES MOTOR RUN?			⊠ YE	S [□NO	C	AN IT I	I IT BE DRIVEN?					CO	COLLISION DAMA			Ξ?	☐ YE	⊠ NO		
				PHYSICAL APPEARANCE																	
ВОДУ	FDONT	GD	FR	PR	N/A	CO	MMENTS	<u> </u>								OPTIONS PWR STEERING					
	FRONT BUMPER HEAD LIGHTS			\boxtimes						D/S				_	AKES						
	HOOD	HOOD		\boxtimes			Sm	all hole	on D/				╛ ̄		⊠ AIR						
				\boxtimes									_ _	☐ HYD ☐ PWR LOCKS							
	GRILL □ D FRONT FENDER □																=	WR L			
	D DOOR			\boxtimes												ᅴ 는	_	WR S		_	
	D DUMP BED			\boxtimes			Ha	s Rust] P	WR M			
	REAR GATE			\boxtimes																IONER EAT D/P	
	TAIL LIGHTS			\boxtimes	lΗ	ΙH														JSPENSION	<u></u>
	P FRONT FENDER			\boxtimes] A	M FM			
	P FRONT DOOR			\boxtimes			Ша	e Duet									☐ TAPE / CD / CB?				
	TOP				lΗ	ΙH										☐ TARP SYSTEM					
TIRES	D FRONT			\boxtimes				% 315/8] T	ANDE			
	D REAR A1 (S/D?)							0 % 11R22.5 SIZE: 0 % 11R22.5 SIZE:									☐ ENGINE BRAKE				
	D REAR A2 (S/D?)			\boxtimes		$\mid \; \mid \; \mid$	□ 80 % 11R22.5 □ 50 % 315/80R2										☐ TOOL BOX FUEL TANKS				
	P REAR A1 (S/D?)			\boxtimes			50	50 % 11R22.5 SIZE:							⊠ SINGLE GAL <u>100</u> □ DUAL GAL						
	P REAR A2 (S/D?)				\boxtimes			25 % 11R22.5 SIZE: 50 % 235/75R17.5 SIZE:						_ _							
	SPARE WINDSHIELD							% 235//: ck chips									│				
SS	_	D FRONT DOOR		\boxtimes				Nock onips							⊠ ALUMINUM						
GLA		REAR WINDOW		\boxtimes									☐ STEEL								
G	P FRONT DOOR MIRRORS] BUD] SPC							
	DASH	110			\boxtimes		Mis	ssing cor	npar					\dashv \triangleright		EXHAUST S/D?					
RIOR	DOOR			\boxtimes		Tea	Tears in upholstery				s		ENSIC	N							
ER	SEAT(S) FLOORING			\boxtimes														⊠ AIR ∐ SPR	ING		
INTE	HEADL] PAC								
	DUMP		\boxtimes			_	s Rust		NTO						☐ LIFT/TAG AXLE						
MECHANICAL	ENGIN	GD	FR 🖂	PR	UKN	N/A	A COM	MEI	NTS:						<u> </u>	_	RTICI BED C				
		TRANSMISSION		\boxtimes													_	VET K			
		CLUTCH		\boxtimes												_ []				
		DIFFERENTIALS BRAKES		\boxtimes				-								_	J T				
		BRAKES FRONT END			ᅡ님	1 1	15								ว่						
	REAR END												╗┋								
BATTERY/ELECTR COMMENTS:								New	6/20)24							<u> </u>				
	IVIIVIE IN I S	. .																			
								6/19/20	124												

EMPLOYEE'S FULL NAME (PLEASE PRINT)

DATE

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.