RTR Services Inc.							RTR #: 405343						3436	6							
BOX TRUCK CONDITION REPORT									ACCOUNT NUMBER:												
		2016	RI	NAII	ES.	Unknown				VIN#: 3ALACWDTXGDHB5391											
YEAR:				GV		25.500		OX HEIGH	J.T.	VIN#:	_			1		D/	OV 14	IDTU			
MAKE:		M2 106	Freightliner			-,		OX REIGH							BOX WIDTH INTERIOR: Gray						
MODEL:			Cummins ISB 6.7L		WHEELB/		ASE:			COLOR: EXTERIOR: White  KEYS: IGNITION: ☑ YES ☐ NO • DOOF											
ENGINE: TRANS:		Automatic			1 CAS 5				NTIFREEZE TESTED: \( \text{YES} \text{ NO} \)						RATING:						
DOES MOTO					□ NO			IT BE DRIVE		1		1			ON DAMAGE?				NO NO		
DOES MOTOR ROW!			3   L			ANTIL			APPEARANCE					ION DA	AMPAGE:				⊠ NO		
			GD	FR	PR	N/A	CON	IMENTS											OPTI	ONS	
BODY	_	BUMPER		$\boxtimes$			Chip	ped							_	PWR S	TEE	RING			
	HEAD	LIGHTS		$\boxtimes$														AKES ⊠ AIR			
	TURN SIGNALS			$\boxtimes$													HYD				
		GRILL D FRONT FENDER		$\boxtimes$													=	PWR LOCKS PWR WINDOWS			
	D DOO	D DOOR		$\boxtimes$													_	PWR S			
	D BOX	D BOX															_	PWR N			
		REAR BUMPER TAIL LIGHTS		$\boxtimes$													_			TIONER EAT D/P	
	REAR	REAR PANEL		$\boxtimes$														AIR RII	DE S	USPENSI	ON
	_	P FRONT FENDER P FRONT DOOR		$\boxtimes$													_	AM FM TAPE /		_	
	P BOX			$\boxtimes$			Dented										SLEEPER SIZE?			_	
	TOP D FRONT			$\boxtimes$			<b>50</b> 0	50 % 11R 22.5 SIZE:						_	TRANS		ENT ROO	F			
TIRES		D REAR A1 (S/D?)		$\boxtimes$				0 % 11R 22.3												LIGHT	
	D REA	D REAR A2 (S/D?)				$\boxtimes$		-	SIZE								_	SIDE D		1	
	PREA	P FRONT P REAR A1 (S/D?)		$\boxtimes$				6 11R 22.9 0 % 11R 2									FUE	L TANK ⊠ SIN		GAL	
	P REAR A2 (S/D?)					$\boxtimes$	9/	% SIZE:					DUAL GAL								
-	SPARE					9	<u>6</u> S	SIZE	<u>:</u>								MUD F	LAP	S		
GLASS	D EBO	D FRONT DOOR REAR WINDOW P FRONT DOOR		$\boxtimes$																UM	
	REAR			$\boxtimes$											STE ☐ BU						
0	MIRRORS			$\boxtimes$																	
	DASH	DANELC					Electrial issue/short						EXHAUST S/D?								
OR	DOOR PANELS SEAT(S)			$\boxtimes$			Torn	Torn									SUSPENSION				
INTERI	FLOOF	FLOORING HEADLINER SLEEPER																			
ĮΞ	SLEEP																	☐ PAE		XLE	
	BOX	· -		$\boxtimes$														<b>ENGIN</b>	E BR	AKE	
MECHANICAL	ENGIN	E	GD	<u>FR</u> ⊠	PR	UKN	N/A	COMM	ΛΕΝ.	TS:								TOOL			
		TRANSMISSION																RAMP			
	CLUTO	CLUTCH DIFFERENTIALS															$\square$	LIFT G	ATE		
	BRAKE	BRAKES															$\exists$				
		FRONT END		$\boxtimes$																	
_	REAR END BATTERY/ELECTR																				
	REFRIC	GERATION				<u> </u>	$\boxtimes$			T1						41.		0:		-1- /	1
COMMENTS: Mileage unknown, unverified. Blows smoke and exhaust. The mileage reading isn't showing on the dash. Suspect an electrical issue/short with the instrument cluster and have ruled out fuses, battery cables and connections. Odometer was at 138,175 on 3/10/20.																					
05/21/2024																					
		EMPLOYEE'S FUL						DATE	E	<del></del>	_				PLOYEE"						
		By si	gnature ab	ove I do	nereby	centry all in	irormation	contained wit	ıının ti	nis report to be	e true	and accura	ice to the	e pest o	or my kno	wiedge	e at pre	sent.			