RTR Services Inc.						ormae fo				RTR #: 405344					48				
LOADER					NO.		No comment of		P	ACCOUNT NUMBER: ACCOUNT NAME:									
WHEEL/TRACK CONDITION REPORT										ACCC	INUV	NAME:							
				VIN/SN: 6206776															
YEAR: 2016 MAKE: Tigercat																			
	MODEL:	Tigercat 620E		☑ WHEEL   ☐ TRACK     COLOR:   EXTERIOR:     Y				Yellow			INTER	PIOP:							
	ENGINE:									N/Δ • DC	OR:								
	TRANS:	Hyd			FUEL:   DIE					NO ☐ N/A · DOOR: ☐ YES ☒ NO ANTIFREEZE TESTED: ☐ YES ☒ I									
HRS: 12,089					DOES IT RUN				⊠ NO	·		CAN IT BE	☐ YES 🖂 N			<u> </u>	UNK		
		12,007			7020	, II II II I			AL APPEA			.,						01111	
			GD	FR	PR	N/A	COM	MENTS								OPTIO	NS		
ВОДУ	FRONT HEAD LIGHTS															STEE	RING		
																BRAK			
	HOOD TURN SIGNALS														_	LOSED	-		
	GRILL		ΙH		1 🖯											CONDI		R	
	L FRONT FENDER					$\boxtimes$								$\boxtimes$	HEA				
	L DOOR L REAR PANEL						Loose	e (poss	ibly miss	ing hinges	5)					RIDE S		ucio.	
	SAFETY LIGHTS		1 H	ᅵ片										님		RIDE S		NOION	
	REAR															E DECK			
	TAIL LIGHTS													$\boxtimes$	-	PLAYER			
	FRAME TURN SIGNALS													$\ \cdot\ $	MUE 2WD	FLAPS	5		
	R FRONT FENDER		$\vdash \vdash$	H	╁╁		1								4WD				
	R FRONT DOOR			$\boxtimes$										$\boxtimes$	PTO				
	R REAR PANEL WORK LIGHTS															KET SI CK COL			
	TOP		1			lΗ								$\ \cdot\ $		CK WIE			
<u></u>		L FRONT		$\boxtimes$			35 %		SIZE:						ROP				
TIRES	L REAR						35 %		SIZE:					$\boxtimes$	Blad	le			
₽	R FRONT R REAR						35 % 35 %		SIZE:										
		WINDSHIELD					Crack		OILL.					1 🗖					
SS	L DOOR			$\boxtimes$															
GLAS		REAR WINDOW R DOOR					Crack	ed						$\ \cdot\ $					
0		MIRRORS			lΗ	ΙH								lH					
~		DASH/GUAGES					Dama	ged jo	ystick										
ERIOR	DOOR PANELS SEAT CARPET/MAT																		
_														님					
Ż		CONTROLS												┪┪					
				FR	PR	UKN	N/A	COI	MMENTS:										
	ENGINE TRANSMISSION		$\parallel \parallel$	$\parallel$		$\boxtimes$		-											
آ		CLUTCH DIFFERENTIAL 2 <sup>ND</sup> DIFFERENTIAL			1														
MECHANICAL																			
Ι¥							1												
谅		UNDERCARRIAGE BRAKES		$\parallel$	1 🗟		18												
Ē		FRONT END				$\boxtimes$													
		REAR END BATTERY/ELECTR					1												
COMMENTS: Hours unverfied.PTO Pump is damaged.																			
33			1	J . ui	p 13 u	amaget	<b></b>												
							9/1/	/24											
	EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE												-						
						ertify all info	rmation cor			t to be true an	d accur	rate to the best o						_	