RTR Services Inc. BOX TRUCK									RTR #: 4053890					8			
CONDITION REPORT								ACCOUNT NAME:									
		2012		MIL	.ES	Unknov	vn		VIN#:	1FVACWD1	TOCDBD60	51					
MAKE:		Freightliner		GV	<b>GVW</b> : 26,000			X HEIGHT	9'	BOX LEN	IGTH 26'		BOX V	VIDTH	102	"	
MODEL:		M2 106		WH	WHEELBASE:					OLOR: EXTERIOR: White			INTERIOR: Gray			iray	
ENGINE:		Cummins ISB 6.7L		HP					KEYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR: [								
TRANS:		Automatic					AS 🛛 DIESEL		NTIFREEZE TESTED: ☐ YES ☒ NO			RATIN	1				
	DOES M	OTOR RUN?	☐ YE	S	⊠ NO	C.		E DRIVEN	N? │ □ YES │ ⊠ NO │ COLLISION DAM/ NL APPEARANCE				/IAGE?	AGE?   ⊠ YES   □ NO			
			GD	FR	PR	N/A		MENTS	LAITLANA	INCL					OPTIO	ONS	
ВОДУ	FRONT BUMPER							Scuffed up									
		HEAD LIGHTS HOOD TURN SIGNALS											BRA	BRAKES  ⊠ AIR □ HYD			
	GRILL						0"							PWR L			
	D FRONT FENDER D DOOR			$\boxtimes$			Scurre	ed/scratch	<u>1ea</u>				$\exists \exists$	PWR V			
	D BOX			$\boxtimes$		Damage, spray painted							☐ PWR MIRRORS				
		REAR BUMPER TAIL LIGHTS												<ul><li></li></ul>			
		TAIL LIGHTS REAR PANEL		$\boxtimes$			Dente	Dented						☐ ☐ AIR RIDE SUSPENSION			
		P FRONT FENDER P FRONT DOOR					Dama	ged, miss	ing hard co	ver				AM FM		-	
		P BOX					Dente	d					$\exists \exists$	SLEEP			
	ТОР				$\boxtimes$			damaged								ENT ROOF	
TIRES		D FRONT D REAR A1 (S/D?)			$\boxtimes \boxtimes$				22.5 SIZE: R/22.5 SIZE	<u> </u>				E-TRA			
	D REAR A2 (S/D?)					$\boxtimes$	%	SI	ZE:	-				SIDE D	OOR	-	
		P FRONT							22.5 SIZE: R/22.5 SIZE	:-			FUE	L TANK	_	GΔI	
						$\boxtimes$	%	SI	ZE:	•				⊠ DUA	AL GA	AL <u>50</u>	
	SPARE											⊠ MUD FLAPS WHEELS					
GLASS	D EDO	D FRONT DOOR REAR WINDOW		$\boxtimes$									- VVIII		JMINU	JM	
	REAR													⊠ STE			
	P FRONT DOOR MIRRORS			$\boxtimes$									-				
INTERIOR	DASH	DOOR PANELS SEAT(S) FLOORING		$\boxtimes$										EXHAL	JST S	/D? <u>S</u>	
													SUS	SPENSION IN			
	FLOOR			$\boxtimes$											RING		
		HEADLINER SLEEPER											$\dashv$	☐ PAI		/I E	
	BOX						Supp	orts loose	and box de	nted with a	hole		<b>∃</b>	ENGIN			
	ENCIN		GD	FR	PR	UKN	N/A	COMME						TOOL		VI E	
یا		ENGINE TRANSMISSION					$\parallel$	Parts in	Cau				$\exists \exists$	RAMP	AG A	<b>ALE</b>	
MECHANICAL		CLUTCH												LIFT G	ATE		
		DIFFERENTIALS BRAKES															
	FRONT	FRONT END		$\boxtimes$													
	REAR END																
	REFRIC	IGERATION															
CC	OMMENTS	6: Mileage un	known/	unver	ified.	Odomet	er repor	ted to be	188,703 on (	)9/14/2020. <sup>*</sup>	The under	carriage	has rus	st.			
	06/24/2024																
		EMPLOYEE'S FUL						DATE									
		By si	gnature ab	ove I do	nereby	centry all in											