RTR Services Inc.						П				RTR #: 406111						0					
HEAVY TRUCK											ACCOUNT NUMBER:										
CONDITION REPORT					و					ACCOUNT NAME:											
YEAR:		2017			LES	593,94	593,946				VIN#: 1XPBD49XXHD409713			13							
MAKE:		Peterbilt		GV	GVW : 52,000		LIC	LICENSE:					ST: T		TAGS:	MON	ГН		YR:		
MODEL:		579		Wi	WHEELBASE:				COLOR: EX		EXTI	TERIOR: White			INTE	RIOI	IOR: Tan				
ENGINE:		Cummins	HP	45	50				Sleep	eeper KEYS: IGNIT			IGNITION	I: 🛛 YES	: 🛛 YES 🗌 NO • DOOR: 🛭				S 🗌 NO		
TRANS:		Automatic	FU	EL: [GAS	☑ DIESEL AI			ANTI	NTIFREEZE TE		ESTED: ☐ YES ⊠ NO		NO	RATII	NG:	G:				
DOES N		OTOR RUN?	RUN? XES		□ NC)	CAN I	AN IT BE DRI					☐ NO COLLISION DA		SION DA	MAGE?)	☐ YES	⊠ N	Ю	
								PH	YSIC/	AL AF	PPEARAN	ICE									
ВОДУ	EDONE	DUMBER	GD	FR	PR	N/A		COMMENTS								-		IONS			
	HEAD	BUMPER					Lo	Loose. Inside brackets broken. Scuffed.													
	HOOD	2101110	<u> </u>												□ ⊠ AIR						
	TURN S	TURN SIGNALS		\boxtimes											☐ HYD						
	GRILL	GRILL D FRONT FENDER				<u> </u>											WR LOC				
	D PROI		\boxtimes			Sid									WR WINDOWS WR SEATS						
	D SLEEPER				lΗ	1 7	310	Side militor broken a back side or casing is missing.								$\dashv \exists$					
	REAR	REAR BUMPER																IR CONI		ER	
		TAIL LIGHTS																IR RIDE			
		REAR PANEL P FRONT FENDER				+ =	Cr	Cracked. Chipping Paint								$-\parallel$					
	_	P FRONT DOOR					- 01	acked	. 0	ppiii	1 1 ann					SLIDING 5TH WHEEL					
	P SLEEPER																	M FM R			
		TOP				+											TAPE / CD / CB? CD_				
TIRES	D FRONT D REAR A1 (S/D?)							20 % 295/75R22.5 SIZE: 60 % 295/75R22.5 SIZE:									□ SLEEPER SIZE? □ ELECTRICAL PIGTAIL				
		D REAR A2 (S/D?)						70 % 295/75R22.5 SIZE:								$\exists \ \exists$					
	P FROM	P FRONT		\boxtimes				50 % 295/75R22.5 SIZE:								FU	FUEL TANKS				
		P REAR A1 (S/D?)						60 % 295/75R22.5 SIZE:									☐ SINGLE GAL ☑ DUAL GAL				
	P REAR A2 (S/D?) SPARE						70	70 % 295/75R22.5 SIZE:							\dashv		J DUAL UD FLA				
SS	WINDSHIELD				Ø		Cr	acked									IEE	_	. •		
	D FROI	D FRONT DOOR		\boxtimes													=	ALUMI			
GLAS	REAR	REAR WINDOW P FRONT DOOR													STEEL □ BUD						
٥	MIRRORS													_] SPOKI	E					
	DASH						Mi	Missing Buttons						E	XHAUS1	S/D?	<u>s_</u>				
RIOR	DOOK	PANELS		\boxtimes									SU	_	ENSION						
ERI	SEAT(S	SEAT(S)					Sta	Stained							AIR	_					
NA	HEADI	CARPET HEADLINER		\boxtimes] SPRIN] PAD	G		
_	SLEEP					Sc	Scuffs/Stains									ANDEM	AXLE				
MECHANICAL	FNOR	_	GD	FR	PR	UKN		N/A COMME										NGINE E			
	ENGINI					\parallel			Coola	ınt le	ak. Tire P	ress	ure Ligi	nt on		┦믬		OOL BO FT/TAG			
	CLUTC	TRANSMISSION CLUTCH			\parallel											ᅱᆸ		ET KIT	AALL		
	DIFFER	DIFFERENTIALS		\boxtimes																	
	BRAKE	BRAKES			ᅵᄆ			<u> </u>													
Z	REAR	FRONT END REAR END			\parallel	\parallel															
	REAR END U				$ \; \exists$			Replaced			d 07/2024				ᅱᆸ						
COMMENTS: Mileage unverified. Truck originally came with no passenger seat.																					
<u> </u>																					
								6/27	/202	4											
		EMPLOYEE'S FULL					informati		DAT	E	is report to be	- truo	and accura		MPLOYEE'S			nt .		_	
		by Sig	griaiule di	ove i di	, neten)	ociuly dli	ııııvıIIIdli	ioni conta	anieu W	rami tili	is report to be	ะแนะเ	unu autuliä	to to the nes	to my know	iouye ai p	COU	n.			