RTR Services Inc. BOX TRUCK CONDITION REPORT										RTR #: 4063176 ACCOUNT NUMBER: ACCOUNT NAME:									
YEAR: 2015			MIL		248,687	<u> </u>			VIN#: 1FVACWDTXFHGG4273										
MAKE: Freightliner			GVW:		25,500	во	BOX HEIGH		10'	BOX LENGTH 26'		26'	BOX WIDTH 9'						
MODEL: M2				WH	EELB	ASE:				COLOR:	EXTERIOR:	Wh	ite	INT	INTERIOR: Gray				
ENGINE: Cummins ISB 6.7L			HP			KE			EYS: IGNITION: 🛛 YES 🗌 NO 🔸 DOOR: 🛛										
TRANS: Automatic				FUEL: 🗌 GAS 🗵			L	AN'						RATING:					
DOES MOTOR RUN?				S [NO 🛛	CA	CAN IT BE DRIVEN								IAGE?				
				50											OBTIONS				
BODY	FRONT	GD	FR	PR	N/A	COMMENTS								OPTIONS					
	HEAD LIGHTS			\boxtimes											BRAKES				
	HOOD TURN SIGNALS			\boxtimes			Crack	s & Scr	atc	ches					⊠ AIR □ HYD				
	GRILL			\boxtimes															
	D FRONT FENDER			\boxtimes			Loose, scratched, dings PWR								PWR WI	-	VS		
	D DOOR D BOX			\boxtimes			Scratches									PWR SEATS PWR MIRRORS			
	REAR BUMPER															AIR CONDITIONER			
	TAIL LIGHTS			\boxtimes			A											_	
	REAR PANEL P FRONT FENDER				⊢⊢												IDE SUSPENSION		
	P FRONT DOOR			\boxtimes															
	P BOX			\boxtimes			Ton	ornor de							□ SLEEPER SIZE?				
	TOP D FRONT							orner da								E-TRAC			
	D REAR A1 (S/D?)						50/50 % 11R22.5 SIZE:						BOX DOME LIGHT						
TIRES	D REAR A2 (S/D?) P FRONT					\square	% SIZE: 50 % 11R22.5 SIZE:					-	_ SIDE DOOR FUEL TANKS						
	P REAR A1 (S/D?)			\boxtimes				% 11R22.3							SINGLE GAL <u>100</u>				
	P REAR A2 (S/D?)					\boxtimes		% SIZE:							DUAL GAL				
	SPARE WINDSHIELD						Crack	% SIZE: Cracked				MUD FLAPS WHEELS							
GLASS	D FRONT DOOR			\boxtimes			Clacked												
	REAR WINDOW			\boxtimes													L		
G	P FRONT DOOR MIRRORS			\boxtimes												🗌 BUD 🗌 SPOI	٢E		
	DASH														X I	EXHAUS	ST S/D	? <u>S_</u>	
Ř	DOOR PANELS SEAT(S) FLOORING			\boxtimes									SUSPENSION						
RIOR				\boxtimes									_		🗌 AIR 🖾 SPRI	NG			
INTE	HEADLINER			\boxtimes												🗌 PAD			
-	SLEEPER BOX			\square	\square										□ TANDEM AXLE				
			GD	FR	PR	UKN	N/A	COMM	<u>NE</u> N	NTS:					<u> </u>	TOOL B	ox		
MECHANICAL	ENGINE					\boxtimes		No T		- and -							G AXL	E	
	TRANSMISSION CLUTCH					\square	\square	No Tra	ans	code					_	RAMP LIFT GA	TE		
	DIFFERENTIALS					\boxtimes													
	BRAKES FRONT END					\boxtimes													
	FRONT END REAR END					\boxtimes													
	BATTERY/ELECTR							Replace		ed 8/2024									
REFRIGERATION I <																			
Displaying codes "no trans" and "6H 33".																			
	7/17/2024																		

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107