RTR Services Inc.		RTR #: 4063742		
GENERAL EQUIPMENT		ACCOUNT		
CONDITION REPORT			ACCOUNT NAME:	
YEAR:	2020			
MAKE:	Dynapac	☐ YES ⊠ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:	CC1000	☐ OPERATIONA	L	
SN:	10000443HLA025831	NON OPERATIONAL NON OPERATIONAL		
POWER:	Kubota D1105 Diesel	UNTESTABLE		
DESCRIPTION:	Double Drum Vibrator	y Roller		
SHOT / COUNT / HOUR: 347 Hours				
NOTES / COMMENTS: S/N: 10000443HLA025831. Possible battery terminal wire cut. Was able to tach terminal to get hour meter.				
DTD C	andaa laa		DTD #.	
	ervices Inc.		RTR #:	
GENERAL EQUIPMENT		ACCOUNT		
	ON REPORT		ACCOUNT NAME:	
YEAR:			T =	
MAKE:		☐ YES ☐ NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		OPERATIONAL		
SN:		□ NON OPERATIONAL		
POWER:		UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
RTR Services Inc.				
GENERAL EQUIPMENT		ACCOUNT		
CONDITION REPORT				
	ON REPORT		ACCOUNT NAME:	
YEAR:			FOURDMENT WAS IN USE AT THE TIME OF RESOVERY	
MAKE:		YES NO	EQUIPMENT WAS IN USE AT THE TIME OF RECOVERY	
MODEL:		☐ OPERATIONAL		
SN:		□ NON OPERATIONAL		
POWER:		UNTESTABLE		
DESCRIPTION:				
SHOT / COUNT / HOUR:				
NOTES / COMMENTS:				
06/17/2024				
UO/ 17/2U24 EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE				
EMPLOYEE'S FULL NAME (PLEASE PRINT) By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.				