RTR Services Inc. HEAVY TRUCK CONDITION REPORT										RTR #: 407153 ACCOUNT NUMBER: ACCOUNT NAME:					8		
YEAR: 2017			MIL	ES	207,83		VIN#: 1NPXL70X4HD387841										
MAKE:		Peterbilt		GV	GVW:		LICENSE:				ST:		TAGS:	MONT	H	YR:	
MODEL:		389		WH	WHEELBASE:				C	OLOR: EXTERIOR: White /		/ Gray	INTERIOR:		Tan		
ENGINE:		Cummins ISX12		HP		E	BODY TY	ODY TYPE:		Truck	KEYS: IGNITION: 🛛 YES						
TRANS:		15 Speed Manual		FU	FUEL: 🗌 GAS				ANTIF	NTIFREEZE TESTED: 🗌 YE		YES 🖂	NO	RATIN	ATING:		
	DOES M	OTOR RUN?	🛛 YE	<b>s</b> [		C	AN IT BE			🛛 YES		COLL	ISION DA	MAGE?			
PHYSICAL APPEARANCE																	
	FRONT	BUMPER	GD	FR	PR	<u>N/A</u>	COMM	IENTS	5						OP PWR ST	TIONS FERING	
BODY	HEAD LIGHTS HOOD TURN SIGNALS GRILL			$\boxtimes$											KES		
				$\boxtimes$											⊠ AIR ∏ HYD		
																скѕ	
	D FRONT FENDER			$\boxtimes$											PWR WI		
	D DOOR D SLEEPER														PWR SE	-	
	REAR BUMPER															DITIONER	ł
	TAIL LIGHTS			$\boxtimes$												E SEAT D/	
	REAR PANEL P FRONT FENDER													┥Н		E SUSPEN	
	P FRONT DOOR			$\boxtimes$												5 <sup>TH</sup> WHEE	
	P SLEEPER																
TIRES	TOP D FROI	лт		$\boxtimes$		╎╎	60 %	315/80	)R22.5	SIZE:					TAPE / C SLEEPE		
	D REAR A1 (S/D?)				$\square$		00/00	% 11F	R22.5 S	SIZE:						ICAL PIGT	AIL
	D REAR A2 (S/D?) P FRONT P REAR A1 (S/D?)								R22.5 S						GLAD H	-	
				$\square$				60 % 315/80R22 10/00 % 11R22.							L TANKS	LE GAL	
		R A2 (S/D?)						% 11F	R22.5 S	SIZE:						. GAL	
	SPARE							%	SL	ZE:					MUD FL/ EELS	APS	
SS	WINDSHIELD D FRONT DOOR			$\boxtimes$												IINUM	
マ REAR の P FRC MIRR( DASH		WINDOW		$\boxtimes$												L	
		NT DOOR		$\boxtimes$										_		Ē	
		113														T S/D? <u>S</u>	_
ERIOR		PANELS		$\boxtimes$										SUS	PENSION	ı	
ER	SEAT(S												_	□ AIR ⊠ SPRII			
IN	HEADL													_		NG	
	SLEEP	SLEEPER				$\square$									TANDEN		
MECHANICAL	ENGINE		GD	FR	PR		N/A	COM	IMENT	5:					ENGINE		
	-	TRANSMISSION													LIFT/TAG		
	CLUTCH			$\boxtimes$											WET KIT		
	DIFFERENTIALS BRAKES			$\boxtimes$													
	FRONT END			$\boxtimes$													
	REAR END			$\boxtimes$													
BATTERY/ELECTR Image line   COMMENTS: Mileage unverified.																	
<u> </u>																	
							8/0	)5/202	24								
		EMPLOYEE'S FULL	NAME (F	LEASE		)		DA				E	MPLOYEE'S	SIGNATU	RE		

By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present

RTR Services Inc. • 2747 Pence Loop SE, Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107